

# **New Brunswick Train Station – Road Safety Audit**

## **FINAL REPORT**

October 2013

Submitted by

Andy Kaplan

SENIOR TRANSPORTATION SAFETY ENGINEER

Sally Karasov

TRANSPORTATION SAFETY ENGINEER

Michael Weber

ENGINEERING RESEARCHER

Center for Advanced Infrastructure & Transportation (CAIT)

RUTGERS, THE STATE UNIVERSITY OF NEW JERSEY



NJDOT Research Project Manager

Robert Desando

In cooperation with

New Jersey Department of Transportation  
Bureau of Transportation Data Development

and

U.S. Department of Transportation  
Federal Highway Administration

## DISCLAIMER STATEMENT

Road Safety Audit reports provided by Center for Advanced Infrastructure and Transportation staff do not constitute an engineering report. The agency responsible for design and construction should consult a professional engineer licensed in the State of New Jersey in preparing construction documents to implement any of the safety countermeasures in the report.

The contents of this report reflect the views of the authors, who are responsible for the facts and the accuracy of the data presented herein. The contents do not necessarily reflect the official views or policies of the New Jersey Department of Transportation or the Rutgers Center for Advanced Infrastructure and Transportation. This report does not constitute a standard, specification, or regulation. Such document is disseminated under the sponsorship of the Department of Transportation, University Transportation Centers Program, in the interest of information exchange. The U.S. government assumes no liability for the contents or use thereof.

<b>Report No.</b>	<b>Government Accession No.</b>	<b>Recipient's Catalog No.</b>	
<b>Title and Subtitle</b> New Brunswick Train Station Road Safety Audit		<b>Report Date</b> October 2013	
		<b>Performing Organization Code</b> CAIT/Rutgers	
<b>Author(s)</b> Andy Kaplan, Sally Karasov, Michael Weber		<b>Performing Organization Report No.</b>	
<b>Performing Organization Name and Address</b> Center for Advanced Infrastructure & Transportation (CAIT) Rutgers, The State University of New Jersey 100 Brett Road Piscataway, NJ 08854-8014		<b>Work Unit No.</b>	
		<b>Contract or Grant No.</b>	
<b>Sponsoring Agency Name and Address</b> N.J. Department of Transportation 1035 Parkway Avenue P.O. Box 600 Trenton, NJ 08625-0600		<b>U.S. Department of Transportation</b> Research and Special Programs Administration 400 7th Street, SW Washington, DC 20590-0001	
		<b>Type of Report and Period Covered</b> Final Report – October 2013	
<b>Sponsoring Agency Code</b>			
<b>Supplementary Notes</b>			
<b>Abstract</b> This report documents findings and recommendations made by the RSA team on November 30, 2012.			
<b>Key Words</b> RSA, Road Safety Audit		<b>Distribution Statement</b> No Restrictions.	
<b>Security Classification (of this report)</b> Unclassified	<b>Security Classification (of this page)</b> Unclassified	<b>No of Pages</b> 128	<b>Price</b>

Form DOT F 1700.7

CAIT's Transportation Safety Resource Center (TSRC) and New Jersey Local Technical Assistance Program (NJ LTAP) offer a statewide Road Safety Audit (RSA) service at no charge to New Jersey towns and counties. Interested parties can request road surveys conducted by a team of engineers, planners, and law-enforcement officers to help municipalities and counties make cost-effective safety improvements.

A multidisciplinary team of professionals offers assessments on roadway issues such as pedestrian and bicycle safety, intersection analyses, rural roads, human factors, speed management, and sign visibility and retro-reflectivity standards.

RSAs include data-driven considerations and analysis of crashes. To determine the best safety solutions, RSA professionals perform incisive crash data evaluations on the target area using Plan4Safety, TSRC's award-winning crash database and software.

The RSA team provides a final report that includes long- and short-term countermeasure recommendations that fit within the requestor's budget. Furthermore, RSAs pay off. According to the Federal Highway Administration (FHWA), countermeasures applied after RSAs can reduce crashes by approximately 60 percent.

For more information, contact Senior Engineer Researcher Andy Kaplan at [andy.kaplan@rutgers.edu](mailto:andy.kaplan@rutgers.edu)



# TABLE OF CONTENTS

Introduction .....	1
Background .....	2
Road Safety Audit Process .....	7
Information Sources.....	8
RSA Team .....	9
Crash Data.....	11
Corridorwide .....	25
RSA Team Findings.....	25
Easton Avenue (CR 514) & Albany Street (Route 27) .....	31
RSA Team Findings.....	31
Easton Avenue (CR 514) & Wall Street/Little Albany Street.....	42
RSA Team Findings.....	43
Easton Avenue (CR 514) & Somerset Street .....	48
RSA Team Findings.....	48
Somerset Street & College Avenue.....	54
RSA Team Findings.....	54
Somerset Street & Wall Street.....	57
RSA Team Findings.....	57
Somerset Street & George Street (CR 672).....	59
RSA Team Findings.....	59
George Street (CR 672/171) & Albany Street (Route 27) .....	65
RSA Team Findings.....	65
Implementing Recommendations .....	70
Middlesex County .....	72
Long Term .....	72
Medium Term .....	72
Short Term .....	73
City of New Brunswick .....	76
Long Term .....	76
Medium Term .....	76
Short Term .....	76
Potential Funding Sources .....	78
Appendix A – Raw Crash Data.....	A-1
Easton Avenue (CR 514) & Albany Street (Route 27) .....	A-2
Easton Avenue (CR 514) & Wall Street/Little Albany Street.....	A-4

Easton Avenue (CR 514) & Somerset Street .....	A-5
Somerset Street & College Avenue.....	A-7
Somerset Street & Wall Street.....	A-7
Somerset Street & George Street (CR 672).....	A-8
George Street (CR 672/171) & Albany Street (Route 27) .....	A-9
Appendix B – Crash Diagrams .....	B-1
Easton Avenue (CR 514) & Albany Street (Route 27) .....	B-2
Easton Avenue (CR 514) & Albany Street (Route 27) – continued .....	B-3
Easton Avenue (CR 514) & Wall Street/Little Albany Street.....	B-4
Easton Avenue (CR 514) & Wall Street/Little Albany Street – continued.....	B-5
Easton Avenue (CR 514) & Somerset Street .....	B-6
Easton Avenue (CR 514) & Somerset Street – continued .....	B-7
Somerset Street & College Avenue.....	B-8
Somerset Street & Wall Street.....	B-9
Somerset Street & George Street (CR 672).....	B-10
George Street (CR 672/171) & Albany Street (Route 27) .....	B-11
George Street (CR 672/171) & Albany Street (Route 27) – continued .....	B-12
Appendix C – Straight Line Diagrams .....	C-1
Easton Avenue (CR 514).....	C-2
Albany Street (NJ 27) .....	C-3
College Avenue .....	C-4
Somerset Street .....	C-5
Somerset Street .....	C-6
George Street (CR 672) .....	C-7
George Street (CR 171) .....	C-8
Appendix D – Jurisdictional Map .....	D-1
Appendix E – Bus Map .....	E-1
Appendix F – Summary of Proposed Diagrams.....	F-1
Recommendation – Somerset Street & College Avenue .....	F-2
Recommendation – Somerset Street & George Street.....	F-3

## Introduction

---

In 2011, Rutgers' CAIT (Center for Advanced Infrastructure and Transportation) and Dr. Eric Gonzalez, of Rutgers' Department of Civil and Environmental Engineering, successfully partnered with the City of New Brunswick to receive a *Community-University Research Partnership* grant from the Rutgers University Office of Community Affairs. This grant provided funding to analyze traffic and safety in downtown New Brunswick in the vicinity of the train station. The objective of the project was to:

analyze traffic congestion and safety effects of pedestrians and drivers in the vicinity of the New Brunswick train station. The research results will identify low-cost, implementable solutions for the community and Middlesex County in managing multiple modal users, while simultaneously contributing ideas to the transportation engineering field. This project will be led in partnership with the City of New Brunswick's director of planning, community, and economic development. Outcomes will be shared with the City of New Brunswick, County of Middlesex, New Jersey Department of Transportation, the Federal Highway Administration, and Rutgers University

The complex multimodal operations of the surface transportation in the vicinity of the train station were of specific concern to the city. The train station area is adjacent to Johnson and Johnson's headquarters, Rutgers University's College Avenue Campus, and Robert Wood Johnson University Hospital. All of these generate a significant number of vehicles, pedestrians, and bicycles. Additionally, the train station provides access to the cities of New York, Newark, and Trenton, and—through Amtrak—Washington, D.C., and Boston. In addition to the train, there exists significant intra- and inter-county public bus transportation, in addition to the bus system operated by Rutgers University. More so, as Robert Wood Johnson University Hospital is the regional trauma center, there are a significant number of ambulance and paramedic emergency vehicles navigating the city streets. Additionally, both Albany and George Streets and Easton Avenue serve as critical regional arterials connecting western New Brunswick and Franklin Township with the regional highway network. As such, regional and local truck traffic is significant through the corridor.

For the many complexities noted above, this area has a significant amount of multimodal traffic. The city is looking to further capitalize on the activity of the areas, and has designated the train station as the central focus point for transit-oriented development, which is a critical component of New Brunswick's comprehensive economic development plan. The city is interested in identifying ways to improve safety at these locations for vehicles, pedestrians, and bicyclists. This Road Safety Audit will bring together various stakeholders, experts, and roadway/facility owners for improvements that facilitate the safe movement of all roadway users at the intersections around the New Brunswick train station.

## Background

---

The audit focused on seven intersections surrounding the New Brunswick train station, as shown in Figure 1 below, located within Middlesex County, in the City of New Brunswick:




Figure 1 – Map of intersections in RSA study

- Albany Street (Route 27) & Easton Avenue (CR 514)
- Easton Avenue (CR 514) & Wall Street
- Easton Avenue (CR 514) & Somerset Street
- Somerset Street & College Avenue
- Somerset Street & Wall Street
- Somerset Street & George Street (CR 672)
- Albany Street (Route 27) & George Street (CR 672/171)

All of the studied intersections are in an area surrounding the New Brunswick train station. It is bordered by Albany Street (Route 27), George Street, Easton Avenue, and Somerset Street. Albany Street (Route 27), runs 38 miles from southwest to northeast connecting Princeton in Mercer County to Newark in Essex County. Easton Avenue is a major east-west roadway, running south of the Raritan River, connecting U.S. Route 287 near South Bound Brook to Albany Street (Route 27) in the RSA area. George Street and Somerset Street primarily service the New Brunswick area, and both George Street and Albany Street (Route 27) provide access to U.S. Route 18.

The area is urban, a major transportation hub, and abounds with vehicle and pedestrian activity. There are more than eight bus lines that operate within this area, five NJ Transit buses and three New Brunswick shuttles, as well as a significant number of emergency vehicles, as it is adjacent to Robert Wood Johnson University Hospital. The four intersections on the corners are signalized, and the other three (Wall Street at Easton Avenue, College Avenue at Somerset Street, and Wall Street at Somerset Street) are stop controlled.

Somerset Street, College Avenue, Albany Street, and Wall Street/Little Albany Street are under the jurisdiction of the City of New Brunswick, while George Street and Easton Avenue are under the jurisdiction of Middlesex County. Albany Street (Route 27) and Easton Avenue (CR 514), in the vicinity of the RSA, are designated "Urban Principal Arterials." College Avenue and Somerset Street in the area of the RSA are designated "Urban Collectors," and George Street is designated an "Urban Minor Arterial."

The intersection of **Albany Street (Route 27) and Easton Avenue (CR 514)** is a signalized T-intersection with Easton Avenue abutting Albany Street. The train station is in the northeast corner of the intersection. There are two lanes of through traffic on Albany Street northbound and one lane southbound. There is a dedicated left-turn lane from Albany Street northbound to Easton Avenue northbound. There are two dedicated left-turn lanes from Easton Avenue southbound to Albany Street northbound. Immediately north of the intersection is the railroad bridge underpass. There is a significant amount of vehicle and pedestrian activity to and from the train station.




Figure 2 – Albany Street (Route 27) and Easton Avenue (CR 514)






Figure 3 – Easton Ave (CR 514) and Wall Street/Little Albany Street (the northeast corner of the intersection has been significantly revised due to construction)

The intersection of **Easton Avenue (CR 514) and Wall Street** is only 150 feet north of the intersection of Easton Avenue and Albany Street. This is one of the locations where passengers exit the train station to access taxis and waiting cars. Across Easton Avenue from Wall Street is Little Albany Street, which provides access to the emergency entrance to Robert Wood Johnson University Hospital. Both Wall Street and Little Albany Street prohibit left turns and are stop controlled. Easton Avenue is two lanes north of the intersection with parking on both sides. South of the intersection, Easton Avenue has two southbound lanes; one is a dedicated left-turn lane.

The signalized intersection at **Easton Avenue (CR 514) and Somerset Street** is primarily characterized by its highly skewed angle. The crosswalks are long due to this configuration. There is one lane in each direction with parking on both sides of the street. There are three bus routes that pass through the intersection.




Figure 4 – Easton Avenue (CR 514) and Somerset Street



Figure 5 – Somerset Street and College Avenue

**Somerset Street and College Avenue** is a T-intersection with stop-control on College Avenue. Both College Avenue and Somerset Street are two-lane roads with parking on both sides of the street. College Avenue has designated right- and left-turn lanes. There is a walkway (the Gateway) to the train station from this intersection that generates significant pedestrian activity.

The intersection of **Somerset Street and Wall Street**, which is 200 feet west of the intersection with George Street, primarily serves as a taxi stand. There is an active bus stop to the east of the intersection. It is a two-lane road with only right turns permitted.



Figure 6 – Somerset Street and Wall Street



Figure 7 – Somerset Street and George Street

The intersection of **Somerset Street and George Street (CR 672)** is a T-intersection with a sharp angle for the right turn movement from Somerset Street to George Street. There is stop control on Somerset Street. The bus stop on the south side of Somerset Street west of the intersection serves eight routes and is therefore very active. The main entrance to Rutgers' Old Queens building (an historic entrance gate) sits on the northwest corner of the intersection. There is a train underpass on George Street.



**Albany Street (Route 27) and George Street (CR 672/171)** is a right-angle signalized intersection. George Street is a two-lane road with dedicated right, left, and straight ahead lanes in the southbound direction, and dedicated straight ahead and right-turn lanes in the northbound direction with no left turn allowed. Albany Street (Route 27) has two lanes in each direction with parking on the south side of the roadway. There are no left turn or right-turn-on-red movements allowed. The roadway is divided by a grassy median with a pedestrian refuge.




Figure 8 – Albany Street and George Street



## Road Safety Audit Process

The New Brunswick train station RSA followed a process that began with data collection, a crucial task that served as the backbone for recommendations for improvement. At the selected sites, crash data was collected and analyzed using the Plan4Safety crash data analysis tool. The analysis examined crash types, locations, years, road conditions, and contributing circumstances. Using the crash data, crash diagrams, as shown in Appendix B, were produced that showed crash types and locations.



Figure 9 – RSA team conducting site visit

The Road Safety Audit occurred on Friday, November 30, 2012. The day began with a pre-audit meeting that involved the definition of a road safety audit and an overview of the intersections. A presentation was shown detailing the crash analysis and aerial images of the different sites. Following the presentation, all participants were given the opportunity to inspect the sites and utilize their various backgrounds to brainstorm recommended improvements. Immediately following the site visit, the team reconvened to discuss what they observed and to offer suggested recommendations to remedy safety deficiencies.

## Information Sources

---

Several sources of information were used in the RSA process. For example, crash data from 2007 to 2009 \* was examined for trends and patterns. Specific resources used in the analysis included:

- NJDOT Crash Database (2007–2009) \*
- Plan4Safety Crash Data Analysis Tool
- NJTR-1 Crash Reports
- NJDOT Straight Line Diagrams
- Google Earth

\* The crash data from 2007 to 2009 was chosen for analysis because a significant number of crash reports for the years 2009 to 2011 had not yet been recorded in the Plan4Safety database. The conditions during 2007 to 2009 were sufficiently similar to 2009 to 2011.

## RSA Team

The RSA team consisted of 31 members, including police officers, engineers, and planners from different agencies across the state.

Name	Representing	Phone	Email
<b>Carl Blesch</b>	Rutgers' Media Relations	732-932-7084, ext. 616	<a href="mailto:cblesch@ur.rutgers.edu">cblesch@ur.rutgers.edu</a>
<b>Cpt. Will Bourke</b>	City of New Brunswick Fire Department	732-745-5169	<a href="mailto:smoke38@optonline.net">smoke38@optonline.net</a>
<b>Pat Buckelew</b>	City of New Brunswick Police Department	732-745-5005	<a href="mailto:pbuckelew@njbpa.org">pbuckelew@njbpa.org</a>
<b>Carol Byrnes</b>	Middlesex County Transportation Marketing Manager	732-715-6958	<a href="mailto:Carol.Byrnes@co.middlesex.nj.us">Carol.Byrnes@co.middlesex.nj.us</a>
<b>Tom Clark</b>	NJ Transit Rail & Bus Safety	973-491-8080	<a href="mailto:TClark@njtransit.com">TClark@njtransit.com</a>
<b>Pam Fischer</b>	NJTPA	908-619-2786	<a href="mailto:pfischer@njtpa.org">pfischer@njtpa.org</a>
<b>Anthony Gambilonghi</b>	Middlesex County Planning	732-745-3843	<a href="mailto:anthony.gambilonghi@co.middlesex.nj.us">anthony.gambilonghi@co.middlesex.nj.us</a>
<b>Dr. Eric Gonzales</b>	Rutgers' Engineering	848-445-2868	<a href="mailto:eric.gonzales@rutgers.edu">eric.gonzales@rutgers.edu</a>
<b>Ted Green</b>	Rutgers' NJ LTAP	848-445-2916	<a href="mailto:tngreen@rci.rutgers.edu">tngreen@rci.rutgers.edu</a>
<b>David Gregor</b>	Middlesex County Safety Coordinator	609-651-6688	<a href="mailto:davidvgregor@verizon.net">davidvgregor@verizon.net</a>
<b>Tom Guldin, P.E.</b>	City of New Brunswick Engineering	732-745-5056	<a href="mailto:tguldin@cityofnewbrunswick.org">tguldin@cityofnewbrunswick.org</a>
<b>Jonathan Hawkins</b>	Rutgers' VTC	704-576-2367	<a href="mailto:Jonathan.hawkins@rutgers.edu">Jonathan.hawkins@rutgers.edu</a>
<b>Lt. Antoine Johnson</b>	City of New Brunswick Parking Authority	732-545-3118	<a href="mailto:ajohnson@njbpa.org">ajohnson@njbpa.org</a>
<b>Andy Kaplan</b>	Rutgers' TSRC		<a href="mailto:akaplan1@rutgers.edu">akaplan1@rutgers.edu</a>
<b>Sally Karasov</b>	Rutgers' TSRC		<a href="mailto:sally.karasov@rutgers.edu">sally.karasov@rutgers.edu</a>
<b>James Markovich</b>	Middlesex County Engineering	732-745-3283	<a href="mailto:engineering@co.middlesex.nj.us">engineering@co.middlesex.nj.us</a>
<b>Bruce McCracken</b>	Middlesex County Planning		<a href="mailto:bruce.mccracken@co.middlesex.nj.us">bruce.mccracken@co.middlesex.nj.us</a>
<b>Richard Nusser</b>	NJDOT Local Aid	732-625-4294	<a href="mailto:Richard.Nusser@dot.state.nj.us">Richard.Nusser@dot.state.nj.us</a>
<b>Ed O'Connor (for Ray Reeve)</b>	State (DHTS)	609-633-9848	<a href="mailto:edward.o'connor@lps.state.nj.us">edward.o'connor@lps.state.nj.us</a>
<b>Glenn Patterson</b>	City of New Brunswick Planning	732-745-5169	<a href="mailto:gpatterson@cityofnewbrunswick.org">gpatterson@cityofnewbrunswick.org</a>
<b>Angela Quevedo</b>	NJDOT	609-530-4677	<a href="mailto:angela.quevedo@dot.state.nj.us">angela.quevedo@dot.state.nj.us</a>
<b>Anna Rivera</b>	Camino Seguros (Puerto Rican Action Board)	732-828-4510, ext. 128	<a href="mailto:ARivera@prab.org">ARivera@prab.org</a>
<b>William Riviere</b>	NJDOT	609-530-4646	<a href="mailto:william.riviere@dot.stat.nj.us">william.riviere@dot.stat.nj.us</a>
<b>Daniel Sandiford</b>	NJ Transit Rail & Bus Safety	856-968-3826	<a href="mailto:dsandiford@njtransit.com">dsandiford@njtransit.com</a>
<b>Mark Siegle</b>	City of New Brunswick Planning	732-745-5050	<a href="mailto:msiegle@cityofnewbrunswick.org">msiegle@cityofnewbrunswick.org</a>

## RSA Team (continued)

Name	Representing	Phone	Email
<b>Shruti Shrivastava</b>	Rutgers' Engineering		<a href="mailto:shruti.shrivastava89@gmail.com">shruti.shrivastava89@gmail.com</a>
<b>Jennifer Stuart</b>	Rutgers' Transportation	732-932-4807	<a href="mailto:jstuart@aps.rutgers.edu">jstuart@aps.rutgers.edu</a>
<b>Elizabeth Thompson</b>	NJTPA	973-639-8441	<a href="mailto:ethompson@njtpa.org">ethompson@njtpa.org</a>
<b>Brian Tobin</b>	Rutgers' PRP		<a href="mailto:btobin@rci.rutgers.edu">btobin@rci.rutgers.edu</a>
<b>Mike Viscardi</b>	NJ Transit Rail & Bus Safety	973-491-7183	<a href="mailto:mviscardi@njtransit.com">mviscardi@njtransit.com</a>
<b>Michael Webber</b>	Rutgers' TSRC		<a href="mailto:michael.weber@rutgers.edu">michael.weber@rutgers.edu</a>

## Crash Data

---

As of the date of this report, the crash data reported by the NJDOT shows a total of 190 crashes occurring during the three-year period from 2007 to 2009. The crash data from 2007 to 2009 was chosen for analysis because a significant number of crash reports for the period 2009 to 2011 had not yet been recorded in the Plan4Safety database. The conditions during 2007 to 2009 were sufficiently similar to 2009 to 2011 to warrant using the earlier data.

### **RSA Crash Locations**

The intersections around the New Brunswick train station, which were selected for further analyses based on crash data, included:

- Easton Avenue (CR 514) & Albany Street (Route 27)
- Easton Avenue (CR 514) & Wall Street/Little Albany Street
- Easton Avenue (CR 514) & Somerset Street
- Somerset Street & College Avenue
- Somerset Street & Wall Street
- Somerset Street & George Street (CR 672)
- George Street (CR 672/171) & Albany Street (Route 27)

The following tables show detailed statistics of the crash data analyzed for each of the seven intersections studied in the RSA.

### ***Easton Avenue (CR 514) & Albany Street (Route 27)***

As seen from the tables below, approximately 60 percent of the crashes were “Same Direction” crashes, (consisting of “Rear End” and “Side Swipe”) with the remainder a variety of other crash types. Most of the crashes were property damage only. In addition, two-thirds of the crashes occurred during daylight hours and in dry conditions.

Table 3 shows that almost half of the contributing circumstances were “Driver Inattention.” A quarter of the vehicles involved in the crashes were “Making Left Turns” and more than one-third of the vehicles involved in the crashes were either “Going Straight Ahead” or “Stopped in Traffic.”

Easton & Albany		CRASH TYPE									
		Same Direction – Rear End	Same Direction – Side Swipe	Right Angle	Struck Parked Vehicle	Left Turn / U-Turn	Backing	Fixed Object	Pedestrian	Pedal-cyclist	TOTAL
SEVERITY	Property Damage	10	11	2	3	1	1	3			31
	Injury			1					4	1	6
	TOTAL	10	11	3	3	1	1	3	4	1	37

Table 1 – Crash Type vs. Severity

Easton & Albany		LIGHT CONDITION				
		Daylight	Dusk	Dark (Street Lights On / Continuous)	Dark (Street Lights On / Spot)	TOTAL
SURFACE CONDITION	Dry	17	1	8		26
	Wet	6		2	1	9
	Snowy	1				1
	Unknown	1				1
TOTAL		25	1	10	1	37

Table 2 – Light Condition vs. Surface Condition

Easton & Albany		CONTRIBUTING CIRCUMSTANCES									
		Unsafe Speed	Driver Inattention	Failed to Obey Traffic Control Device (Driver / Pedcycle)	Improper Passing	Backing Unsafely	Improper Parking	Failure To Keep Right	None (Driver / Pedcycle)	NULL	TOTAL
PRE-CRASH VEHICLE ACTION	Going Straight Ahead	1	9						3	1	14
	Making Right Turn (not turn on red)		5		1				2		8
	Making Left Turn		11					1	5		17
	Starting in Traffic								1		1
	Slowing or Stopping		2						2		4
	Stopped in Traffic								11		11
	Parked						2		1		3
	Changing Lanes		3								3
	Merging / Entering Lane		2	1					1		4
	Backing					1					1
	Passing		1								1
	NULL									1	1
<b>TOTAL</b>		<b>1</b>	<b>33</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>2</b>	<b>1</b>	<b>26</b>	<b>2</b>	

Table 3 – Contributing Circumstances vs. Pre-Crash Vehicle Action

*Easton Avenue (CR 514) & Wall Street/Little Albany Street*

Easton & Wall		CRASH TYPE								
		Same Direction – Rear End	Same Direction – Side Swipe	Right Angle	Struck Parked Vehicle	Left Turn / U-Turn	Fixed Object	Pedestrian	Pedalcyclist	TOTAL
SEVERITY	Property Damage	3	2	4	3	1	1			14
	Injury	2		1				1	1	5
	<b>TOTAL</b>	<b>5</b>	<b>2</b>	<b>5</b>	<b>3</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>19</b>

Table 4 – Crash Type vs. Severity

Easton & Wall		LIGHT CONDITION		
		Daylight	Dark (Street Lights On / continuous)	TOTAL
SURFACE CONDITION	Dry	13		13
	Wet	3		3
	Snowy		2	2
	Icy	1		1
	<b>TOTAL</b>	<b>17</b>	<b>2</b>	<b>19</b>

Table 5 – Light Condition vs. Surface Condition



As can be seen in the tables above, the predominant crash types were “Same Direction – Rear End” and “Right Angle.” Approximately one-third of the crashes occurred in wet, snowy, or icy conditions, and most of the crashes took place during daylight hours. The table below also shows that more than half of the vehicles involved in the crashes were either “Going Straight Ahead” or “Making a Right Turn (not turn on red).” “Driver Inattention” was the most prominent contributing circumstance.

Easton & Wall		CONTRIBUTING CIRCUMSTANCES									
		Driver Inattention	Failed to Yield Right of Way to Vehicle / Pedestrian	Improper Turning	Following Too Closely	Improper Parking	None (Driver / Pedcycle)	Other Driver / Pedal-cyclist Action	Road Surface Condition	NULL	TOTAL
PRE CRASH VEHICLE ACTION	Going Straight Ahead	2			1		4		2	1	10
	Making Right Turn (not turn on red)	5	1				3		1		10
	Making Left Turn	1		1							2
	Slowing or Stopping	1					2		2		5
	Stopped in Traffic						2	1			3
	Parked					3				1	4
	Merging / Entering Lane						1				1
	Passing	1									1
<b>TOTAL</b>		<b>10</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>3</b>	<b>12</b>	<b>1</b>	<b>5</b>	<b>2</b>	

Table 6 – Contributing Circumstances vs. Pre-Crash Vehicle Action

*Easton Avenue (CR 514) & Somerset Street*

Easton & Somerset		CRASH TYPE								
		Same Direction – Rear End	Same Direction – Side Swipe	Right Angle	Opposite Direction – Side Swipe	Struck Parked Vehicle	Left Turn / U-Turn	Backing	Pedes-trian	TOTAL
SEVERITY	Property Damage	7	11	5	1	7	2	6	1	40
	Injury	1					1		4	6
	TOTAL	8	11	5	1	7	3	6	5	46

Table 7 – Crash Type vs. Severity

Easton & Somerset		LIGHT CONDITION						TOTAL
		Daylight	Dawn	Dusk	Dark (Street Lights Off)	Dark (Street Lights On / Continuous)	Dark (Street Lights On / Spot)	
SURFACE CONDITION	Dry	23	1	2	1	10	1	38
	Wet	3	1			4		8
	TOTAL	26	2	2	1	14	1	46

Table 8 – Light Condition vs. Surface Condition

As can be seen in the tables above, the highest number of crashes by crash type was “Same Direction“(both “Rear End” and “Side Swipe”). But “Right Angle,” “Struck Parked Vehicle,” “Backing,” and “Pedestrian” crashes were also significant. Most of the crashes resulted in property damage only. Only a few of the crashes occurred in wet conditions, and more than 40 percent occurred after dark, or at dawn or dusk. The table below shows that one-third of the vehicles involved in the crashes were partly due to “Driver Inattention” with a wide variation in “Pre-Crash Vehicle Action.”

Easton & Somerset		CONTRIBUTING CIRCUMSTANCES											
		Un-known	Unsafe Speed	Driver Inattention	Improper Passing	Improper Turning	Following Too Closely	Backing Unsafely	Improper Parking	None (Driver/ Ped-cycle)	Other Driver / Pedal-cyclist Action	NULL	TOTAL
PRE-CRASH VEHICLE ACTION	Unknown			1									1
	Going Straight Ahead		2	12	1		1			16	1	1	34
	Making Right Turn (not turn on red)	2		3						1			6
	Making Left Turn		1	4		1				4			10
	Starting From Parking			2						2			4
	Slowing or Stopping			1						2			3
	Stopped in Traffic									9		1	10
	Parking			1									1
	Parked			1					1	8			10
	Merging / Entering Lane			1									1
	Backing			2				3				1	6
	Passing			1	1					1			3
	Other Veh / Cyclist Action			1									1
<b>TOTAL</b>		<b>2</b>	<b>3</b>	<b>30</b>	<b>2</b>	<b>1</b>	<b>1</b>	<b>3</b>	<b>1</b>	<b>43</b>	<b>1</b>	<b>3</b>	

Table 9 – Contributing Circumstances vs. Pre-Crash Vehicle Action

## Somerset Street & College Avenue

Somerset & College		CRASH TYPE						
		Same Direction – Rear End	Same Direction – Side Swipe	Right Angle	Struck Parked Vehicle	Pedestrian	NULL	TOTAL
SEVERITY	Property Damage	2	1	4	1		1	9
	Injury					1		1
	TOTAL	2	1	4	1	1	1	10

Table 10 – Crash Type vs. Severity

Somerset & College		LIGHT CONDITIONS			
		Daylight	Dusk	Dark (Street Lights On / Continuous)	TOTAL
SURFACE CONDITIONS	Dry	4	1	2	7
	Wet			3	3
	TOTAL	4	1	5	10

Table 11 – Light Condition vs. Surface Condition

Somerset & College		CONTRIBUTING CIRCUMSTANCES								
		Unknown	Unsafe Speed	Driver Inattention	Failed to Yield Right of Way to Vehicle/ Pedestrian	None (Driver / Pedcycle)	Other Driver / Pedal-cyclist Action	Other Vehicle Factor	Other	TOTAL
PRE-CRASH VEHICLE ACTION	Going Straight Ahead	1				4			1	6
	Making Right Turn (not turn on red)						1			1
	Making Left Turn	1	1		2		1			5
	Starting in Traffic		1							1
	Slowing or Stopping		1	1		1				3
	Stopped in Traffic			1						1
	Parked							1		1
	Merging / Entering Lane			1						1
	Driverless / Moving							1		1
<b>TOTAL</b>		<b>2</b>	<b>3</b>	<b>3</b>	<b>2</b>	<b>5</b>	<b>2</b>	<b>2</b>	<b>1</b>	

Table 12 – Contributing Circumstances vs. Pre-Crash Vehicle Action

## Somerset Street & Wall Street

Somerset & Wall		CRASH TYPE				
		Same Direction – Rear End	Same Direction – Side Swipe	Right Angle	Struck Parked Vehicle	TOTAL
SEVERITY	Property Damage	1	1	1	2	5
	Injury	1				1
	TOTAL	2	1	1	2	6

Table 13 – Crash Type vs. Severity

Somerset & Wall		LIGHT CONDITIONS		
		Daylight	Dark (Street Lights On / Continuous)	TOTAL
SURFACE CONDITIONS	Dry	4	1	5
	Wet	1		1
	TOTAL	5	1	6

Table 14 – Light Condition vs. Surface Condition

As can be seen from the tables above, there were a variety of crash types but no particular type was dominant. Most of the crashes occurred during daylight hours and in dry conditions.

*Somerset Street & George Street (CR 672)*

Somerset & George		CRASH TYPE							
		Same Direction – Rear End	Same Direction – Side Swipe	Right Angle	Struck Parked Vehicle	Backing	Fixed Object	Pedes-trian	TOTAL
SEVERITY	Property Damage	5	6	2	1	1	2	1	18
	Injury							2	2
	TOTAL	5	6	2	1	1	2	3	20

Table 15 – Crash Type vs. Severity

Somerset & George		LIGHT CONDITION			
		Daylight	Dark (Street Lights On / Continuous)	Dark (Street Lights On / Spot)	TOTAL
SURFACE CONDITION	Dry	7	7	1	15
	Wet	1	3		4
	Icy	1			1
	TOTAL	9	10	1	20

Table 16 – Light Condition vs. Surface Condition

Tables 15 and 16 above show that more than half of the crashes are “Same Direction,” both “Rear End” and “Side Swipe.” Most of the crashes were property damage only. More than half of the crashes occurred in dark conditions and one-quarter of the crashes occurred in wet or icy conditions.

In Table 17, below, the most common “Pre-Crash Vehicle Action” was “Making Right Turn,” which involved slightly less than one-third of all of the crashes. The most common contributing circumstance was “Driver Inattention.”

Somerset & George		CONTRIBUTING CIRCUMSTANCES								
		Driver Inattention	Failed to Yield Right of Way to Vehicle / Pedestrian	Improper Passing	Improper Use / Failed to Use Turn Signal	Improper Turning	None (Driver / Pedcycle)	Other Driver / Pedalcyclist Action	NULL	TOTAL
PRE-CRASH VEHICLE ACTION	Going Straight Ahead	3					1		2	6
	Making Right Turn (not turn on red)	3		1	1		5			10
	Making Left Turn	3	1				2			6
	Making U-Turn					1				1
	Slowing or Stopping						2			2
	Stopped in Traffic	2					3			5
	Parking						1			1
	Parked							1		1
	Backing	2								2
	Passing			1						1
<b>TOTAL</b>		<b>13</b>	<b>1</b>	<b>2</b>	<b>1</b>	<b>1</b>	<b>14</b>	<b>1</b>	<b>2</b>	

Table 17 – Contributing Circumstances vs. Pre-Crash Vehicle Action



*George Street (CR 672/171) & Albany Street (Route 27)*

George & Albany		CRASH TYPE								
		Same Direction – Rear End	Same Direction – Side Swipe	Right Angle	Struck Parked Vehicle	Left Turn / U-Turn	Backing	Pedestrian	Other	TOTAL
SEVERITY	Property Damage	14	13	7	1	1	1	1	2	40
	Injury	5		1	1			5		12
	<b>TOTAL</b>	<b>19</b>	<b>13</b>	<b>8</b>	<b>2</b>	<b>1</b>	<b>1</b>	<b>6</b>	<b>2</b>	<b>52</b>

Table 18 – Crash Type vs. Severity

George & Albany		LIGHT CONDITIONS				
		Daylight	Dusk	Dark (No Street Lights)	Dark (Street Lights On / continuous)	TOTAL
SURFACE CONDITIONS	Dry	34		1	7	42
	Wet	3			4	7
	Snowy		1			1
	NULL	1				1
	Unknown	1				1
<b>TOTAL</b>		<b>39</b>	<b>1</b>	<b>1</b>	<b>11</b>	<b>52</b>

Table 19 – Light Condition vs. Surface Condition

Tables 18 and 19 above show that approximately 60 percent of the crashes are “Same Direction” both “Rear End” and “Side Swipe.” More than 75 percent of the crashes were “Property Damage” only, and more than 75 percent of the crashes occurred in dark conditions. Only a small number of the crashes occurred in wet or snowy conditions.

In Table 20 below, 40 percent of the crashes listed “Driver Inattention” as a contributing circumstance. More than half of the vehicles involved in the crashes were “Going Straight Ahead,” which correlates with “Same Direction” crashes.


George & Albany		CONTRIBUTING CIRCUMSTANCES														
		Un-known	Unsafe Speed	Driver Inattention	Failed to Obey Traffic Control Device (Driver / Ped-cycle)	Failed to Yield Right of Way to Vehicle / Pedestrian	Improper Lane Change	Improper Passing	Improper Turning	Following Too Closely	Backing Unsafely	Improper Parking	None (Driver / Ped-cycle)	NULL	Other	TOTAL
PRE-CRASH VEHICLE ACTION	Going Straight Ahead	3	2	24	1	1				2			21			54
	Making Right Turn (not turn on red)			3					1				6			10
	Making Left Turn	1		1					1				1			4
	Starting From Parking			1												1
	Slowing or Stopping			4									2		1	7
	Stopped in Traffic			1									10			11
	Parked			1								1				2
	Changing Lanes			4												4
	Merging/Entering Lane							1								1
	Backing										1					1
	Passing								1							1
	NULL			1									1	1		3
	TOTAL		4	2	40	1	1	1	1	2	2	1	1	41	1	1


Table 20 – Contributing Circumstances vs. Pre-Crash Vehicle Action


## Corridorwide


### *RSA Team Findings*



The following section details the specific findings of and recommendations made by the RSA team. All recommendations and designs should be thoroughly evaluated by the roadway owner and/or a professional engineer for conformance to codes, standards, and best practices.

Issue: Roadway Markings	Safety Risk	
<p><b>Description:</b> Many of the roadway markings are either faded or weren't replaced when pavement repair was made.</p>	<p>Medium/High</p>	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
<p>Regular maintenance should ensure that the roadway markings are clearly visible to pedestrians and vehicles. (1)</p>	<p>Low</p>	<p>Medium/High</p>
<p>Installation of retro-reflective pavement markings would significantly increase visibility. (2)</p>	<p>Low</p>	<p>Medium/High</p>


Issue: ADA Compliance	Safety Risk	
<b>Description:</b> Pedestrian accommodations, such as ramps and detectable warning surfaces, are not fully ADA compliant.	Medium	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
Plan for full ADA compliance by scheduling upgrades of existing ramps and curbs at crosswalks. (3)	Medium	Medium


Issue: Pedestrian Behavior	Safety Risk	
<b>Description:</b> Pedestrians were observed not using the pedestrian facilities, sidewalks, and crosswalks.	High	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
Improve pedestrian crossings to encourage pedestrians to cross in marked crosswalks. (4)	Medium/Low	Medium

Issue: Lighting	Safety Risk	
<p><b>Description:</b> Lighting was inconsistent, not uniform, and may not address the nighttime visibility needs of both pedestrians and vehicles.</p>	<p>Medium/High</p>	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
<p>Professional staff should conduct a formal engineering review of existing lighting conditions to evaluate where both vehicle and pedestrian level lighting can be enhanced. (5)</p>	<p>Medium</p>	<p>Medium/High</p>

Issue: Signs	Safety Risk	
<p><b>Description:</b> The abundance of signs creates confusion for drivers and pedestrians.</p>	<p>Medium/High</p>	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
<p>Professional engineering staff should conduct a thorough evaluation of existing and required signage to reduce the amount of signage in the intersection and decrease sign clutter. (6)</p>	<p>Low</p>	<p>Medium/High</p>



Issue: Train Station Drop-off and Pick-up	Safety Risk	
<p><b>Description:</b> There are a few unofficial “Kiss-and-Ride” drop-off/pick-up areas in the vicinity of the train station, under the bridge on Easton Avenue and in front of the station on Albany Street. None of these locations have signage or roadway markings to officially designate them for this purpose.</p>	Medium	
<p><b>Description:</b> The area in front of the train station on Albany Street has a “NO STOPPING” sign, yet it is unofficially being used as a pick-up and drop-off area.</p>	Medium	
		
RSA Team’s Recommendation	Cost	Potential Safety Benefit
<p>Professional engineering staff should conduct a thorough evaluation of the train station traffic, including passenger pick-up and drop-off points and locations for taxi stands and private passenger vehicles. (7)</p>	Low	Medium
<p>Evaluate creating a dedicated taxi stand and installing signage in the area under the bridge at northbound Easton Avenue. (10)</p>	Low	Medium


Issue: Bicycles	Safety Risk	
<b>Description:</b> There are no designated accommodations for bicycle travel in the area around the train station.	Medium/High	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
Professional engineering staff should do a full evaluation of bicycle travel in the area around the train station to complement the New Brunswick Bike Lane project. (8) <b>See bikeway map:</b> <a href="http://thecityofnewbrunswick.org/planninganddevelopment/files/Bike-Lanes-2012-20131.pdf">http://thecityofnewbrunswick.org/planninganddevelopment/files/Bike-Lanes-2012-20131.pdf</a>	Low	Medium/High






## Easton Avenue (CR 514) & Albany Street (Route 27)

### RSA Team Findings


The following section details the specific findings of and recommendations made by the RSA team. All recommendations and designs should be thoroughly evaluated by the roadway owner and/or a professional engineer for conformance to codes, standards, and best practices.


Issue: Lighting (Easton/Albany)	Safety Risk	
<p><b>Description:</b> Lighting is inconsistent and not uniform under the railroad bridge, and may not address the nighttime visibility needs of both pedestrians and vehicles.</p>	<p>Medium/High</p>	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
<p>Professional staff should conduct a formal engineering review of existing lighting conditions to evaluate where both vehicle and pedestrian level lighting can be enhanced. (5)</p>	<p>Medium</p>	<p>Medium/High</p>


Issue: Signage (Easton/Albany)	Safety Risk	
<p><b>Description:</b> The abundance of signs in front of the train station creates confusion for drivers and pedestrians.</p>	<p>Medium/High</p>	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
<p>Professional engineering staff should conduct a thorough evaluation of existing and required signage to reduce the amount of signage in the intersection and decrease sign clutter. (6)</p>	<p>Low</p>	<p>Medium/High</p>

Issue: Pole (Easton/Albany)	Safety Risk	
<p><b>Description:</b> An unused broken pole is located in the island curb ramp (on right turn from Easton Avenue to southbound Albany Street).</p>	<p>Low</p>	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
<p>Consider removing the unused broken pole in the island curb ramp (from Easton Avenue to southbound Albany Street). (9)</p>	<p>Low</p>	<p>Low</p>


Issue: Pavement (Easton/Albany)	Safety Risk	
<b>Description:</b> Some drivers were observed swerving around raised manhole covers to avoid hitting them.	Medium	
RSA Team's Recommendation	Cost	Potential Safety Benefit
Identify locations of raised manhole covers and consider resetting the manhole covers to be flush with the pavement. (11)	Medium/High	Medium

Issue: Crosswalk (Easton/Albany)	Safety Risk	
<b>Description:</b> There are many pedestrians crossing the "Kiss-and-Ride" driveway, on Albany Street southbound to and from the train station, but there is no marked crosswalk at that location.	Medium/High	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
Consider installation of a marked crosswalk across the "Kiss-and-Ride" driveway on southbound Albany Street. (12)	Low	Medium/High

Issue: Roadway Markings (Easton/Albany)	Safety Risk	
<p><b>Description:</b> Many of the roadway markings and striped crosswalks on Albany Street and Easton Avenue are faded and not clearly visible to vehicles and pedestrians.</p>	<p>Medium/High</p>	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
<p>Regular maintenance will ensure that the roadway markings are clearly visible to pedestrians and vehicles. (1)</p>	<p>Low</p>	<p>Medium/High</p>
<p>Installation of retro-reflective pavement markings would significantly increase visibility. (2)</p>	<p>Low</p>	<p>Medium/High</p>

<b>Issue: Midblock Crossing (Easton/Albany)</b>	<b>Safety Risk</b>	
<b>Description:</b> Pedestrians were observed not using the pedestrian facilities, sidewalks, and crosswalks on both Albany Street and Easton Avenue.	Medium/High	
		
<b>RSA Team's Recommendation</b>	<b>Cost</b>	<b>Potential Safety Benefit</b>
Improve pedestrian crossings to encourage pedestrians to cross in marked crosswalks. (4)	Medium/Low	Medium/High
Evaluate unofficial crossing locations in the median on Albany Street and consolidate or eliminate them, if possible.(13)	Low	Medium/High




Issue: Pedestrian Accommodations (Easton/Albany)	Safety Risk	
<b>Description:</b> Pedestrian accommodations, such as ramps and detectable warning surfaces, are not fully ADA compliant.	Medium	
<b>Description:</b> There is a raised junction box in the northwest corner, adjacent to the ramp that poses a tripping hazard.	Medium/Low	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
Plan for full ADA compliance by scheduling upgrades of existing ramps and curbs at crosswalks. (3)	Medium	Medium
Consider resetting or relocating the junction box. (14)	Low	Medium

Issue: Pedestrian Buttons (Easton/Albany)	Safety Risk
<b>Description:</b> Pedestrians are required to press a button to activate a walk signal to cross Albany Street.	Medium/High
<b>Description:</b> There is a high volume of pedestrians at this intersection and many were not utilizing the buttons.	Medium/High
<b>Description:</b> Pedestrian buttons are not properly aligned in accordance with ADA requirements.	Medium



RSA Team's Recommendation	Cost	Potential Safety Benefit
To accommodate the high pedestrian volume, consider operating the signal in fixed time or utilizing pedestrian recall and removing pedestrian buttons. (19)	Low	Medium
Schedule realignment of the pedestrian buttons to conform to the 2009 MUTCD requirements. (20)	Low	Medium/Low


Issue: Pedestrian Heads (Easton/Albany)	Safety Risk	
<p><b>Description:</b> Pedestrians crossing Albany Street from the southwest corner, see a walk signal adjacent to the ramp, although the pedestrian head for their crosswalk displays “DON’T WALK.”</p>	Medium/High	
<p><b>Description:</b> Pedestrian heads are not located in the direct line of sight of pedestrians using the crosswalks.</p>	Medium	
		
RSA Team’s Recommendation	Cost	Potential Safety Benefit
<p>Plan to realign and/or limit visibility of the walk signal so pedestrians do not receive conflicting information. (18)</p>	Low	Medium/High
<p>Review the alignment of the pedestrian heads with the crosswalks and sidewalks. (21)</p>	Low	Medium/Low



Issue: Pedestrian Timing/Phasing (Easton/Albany)	Safety Risk
<b>Description:</b> Crossing times may be inadequate under the 2009 edition of the MUTCD.	Medium/High
<b>Description:</b> The signal phasing for pedestrians crossing Albany Street is not intuitive and consequently, pedestrians frequently cross illegally against the left turning traffic from Easton Avenue to Albany Street northbound.	Medium/High




RSA Team's Recommendation	Cost	Potential Safety Benefit
Ensure crossing times are compliant with the 2009 edition of the MUTCD. (15)	Low	Medium/High
Consider rephasing signal timing so that the walk signal across the easterly Albany Street crosswalk comes before the left turn from Easton Avenue southbound to Albany Street northbound. (16)	Low	High
Evaluate adding an all-red, all-way pedestrian crossing at the intersection. (17)	Low	High
To accommodate pedestrian volume, consider operating the signal in fixed time or utilizing pedestrian recall and remove pedestrian buttons. (19)	Low	Medium


Issue: Bicycles (Easton/Albany)		Safety Risk
<b>Description:</b> There are no designated accommodations for bicycle travel in the area around the train station.		Medium/High
<b>Description:</b> There are insufficient accommodations for bicycle parking adjacent to the train station.		Low/Medium
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
Professional engineering staff should do a full evaluation of bicycle travel in the area around the train station to complement the New Brunswick Bike Lane project.(8) <b>See bikeway map:</b> <a href="http://thecityofnewbrunswick.org/planninganddevelopment/files/Bike-Lanes-2012-20131.pdf">http://thecityofnewbrunswick.org/planninganddevelopment/files/Bike-Lanes-2012-20131.pdf</a>	Low	Medium/High
Consider the installation of additional bicycle parking. (22)	Low	Low/Medium

Issue: Merging Buses (Easton/Albany)	Safety Risk
<p><b>Description:</b> Buses have difficulty merging back into traffic from the bus stop just prior to the “Kiss-and-Ride” driveway on Albany Street southbound.</p>	<p>Medium/Low</p>



RSA Team’s Recommendation	Cost	Potential Safety Benefit
<p>Evaluate an alternative to the existing bus stop by revising (as conceptualized below) the striping on Albany Street northbound to increase the width on Albany Street southbound and allow the relocation of the bus stop just past the intersection, after the ramp from Easton Avenue southbound. (24) [See the diagram below.]</p>	<p>Low</p>	<p>Medium/High</p>



Issue: Left-Turn Crashes (Easton/Albany)	Safety Risk	
<b>Description:</b> Crash history indicates a significant number of left-turn crashes.	Medium/High	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
Consider the addition of dotted lane line extension pavement markings, delineating the dual left-turning movement from Easton Avenue southbound to Albany Street northbound. (25)	Low	Medium/High

Issue: Drainage (Easton/Albany)	Safety Risk	
<b>Description:</b> Water drips onto Easton Avenue from the Amtrak bridge creating icy conditions on the sidewalk and roadway in cold weather.	High	
RSA Team's Recommendation	Cost	Potential Safety Benefit
Request that Amtrak make appropriate repairs to the bridge to alleviate the dripping water. (26)	High	High




## Easton Avenue (CR 514) & Wall Street/Little Albany Street

### RSA Team Findings



The following section details the specific findings and recommendations made by the RSA team. All recommendations and designs should be thoroughly evaluated by the roadway owner and/or a professional engineer for conformance to codes, standards, and best practices.


Issue: Drainage (Easton/Wall)	Safety Risk	
<b>Description:</b> Water drips onto Easton Avenue from the Amtrak bridge creating icy conditions on the sidewalk and roadway in cold weather.	High	
RSA Team's Recommendation	Cost	Potential Safety Benefit
Request that Amtrak make appropriate repairs to the bridge to alleviate the dripping water. (26)	High	High

Issue: Lighting (Easton/Wall)	Safety Risk	
<b>Description:</b> Lighting was inconsistent and not uniform under the railroad bridge and may not address the nighttime visibility needs of both pedestrians and vehicles.	Medium/High	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
Professional staff should conduct a formal engineering review of existing lighting conditions to evaluate where both vehicles and pedestrian level lighting can be enhanced. (5)	Medium	Medium/High


Issue: Roadway Markings (Easton/Wall)		Safety Risk	
<b>Description:</b> The crosswalk across Little Albany Street is faded and barely visible.		Medium	
			
RSA Team's Recommendation		Cost	Potential Safety Benefit
Regular maintenance should ensure that the roadway markings are clearly visible to pedestrians and vehicles. (1)		Low	Medium/High
Ensure that the missing crosswalk at Little Albany Street is clearly marked. (27)		Low	Medium

Issue: Pedestrians (Easton/Wall)		Safety Risk	
<b>Description:</b> Pedestrian accommodations, such as ramps and detectable warning surfaces, are not fully ADA compliant.		Medium	
<b>Description:</b> After exiting the stairs from the train station, many pedestrians cross Easton Avenue at that location despite there being no marked crosswalk.		Medium	
RSA Team's Recommendation		Cost	Potential Safety Benefit
Plan for full ADA compliance by scheduling upgrades of existing ramps and curbs at crosswalks. (3)		Medium	Medium
Installation of a marked crosswalk across Easton Avenue south of the intersection would increase the safety of pedestrians who are crossing at this location as well as alert motorists to a pedestrian crossing. (28)		Low	Medium

Issue: Parking (Easton/Wall)	Safety Risk	
<p><b>Description:</b> There is Illegal parking on southbound Easton Avenue, just north of Little Albany Street, restricting visibility.</p>	<p>Medium</p>	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
<p>Pavement markings would more clearly delineate the "NO PARKING" zone. (29)</p>	<p>Low</p>	<p>Medium</p>
<p>Consider installation of bulb-outs (painted, curbed, or stanchions), which would shorten the crosswalk and help delineate the allowed parking. (30)</p>	<p>Low-Painted or Stanchions; Medium-Curbed</p>	<p>Medium/High</p>

Issue: Signage (Easton/Wall)	Safety Risk	
<b>Description:</b> There is no “NO LEFT TURN” sign on far-left side when exiting from Wall Street onto Easton Avenue southbound.	Medium	
<b>Description:</b> There is an unused broken pole on Easton Avenue, just north of Little Albany Street.	Low	
		
RSA Team’s Recommendation	Cost	Potential Safety Benefit
Consider installing a “NO LEFT TURN” sign in the far-left corner (for traffic exiting Wall Street onto Easton Avenue southbound) in conformance with the MUTCD. (31)	Low	Low
The broken pole on southbound Easton Avenue, north of Little Albany Street, should be removed. (32)	Low	Low




Issue: Taxi Stand (Easton/Wall)		Safety Risk	
<p><b>Description:</b> The area under the bridge on northbound Easton Avenue, south of Wall Street and adjacent to the train station stairway, is being used as an unmarked taxi stand for passengers disembarking from the train.</p>		Medium	
<p><b>Description:</b> There is an unofficial passenger drop-off and pick-up area along Little Albany Street west of the intersection.</p>		Low/Medium	
			
RSA Team's Recommendation		Cost	Potential Safety Benefit
<p>Professional engineering staff should conduct a thorough evaluation of the train station traffic, including passenger pick-up and drop-off points and locations for taxi stands. (7)</p>		Low	Medium
<p>Evaluate creating a dedicated taxi stand and installing signage in the area under the bridge at northbound Easton Avenue. (10)</p>		Low	Medium

## Easton Avenue (CR 514) & Somerset Street

### *RSA Team Findings*

The following section details the specific findings and recommendations made by the RSA team. All recommendations and designs should be thoroughly evaluated by the roadway owner and/or a professional engineer for conformance to codes, standards, and best practices.

Issue: Right Turns (Easton/Somerset)	Safety Risk	
<p><b>Description:</b> Right turning vehicles from Easton Avenue, in both directions, may have difficulty making the maneuver due to the tight radius.</p>	<p>Medium/Low</p>	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
<p>Conduct a turning analysis to evaluate turning movements and potentially revise intersection striping to include head-to-head left-turn lanes.(33)</p>	<p>Low</p>	<p>Medium</p>


Issue: No Right Turn on Red (Easton/Somerset)	Safety Risk	
<b>Description:</b> Crash history indicates a significant number of crashes involving pedestrians.	Medium/High	
RSA Team's Recommendation	Cost	Potential Safety Benefit
Consider prohibiting right turns on red and place MUTCD compliant signage on all four corners. (34)	Low	Medium/High


Issue: Left Turns (Easton/Somerset)	Safety Risk	
<b>Description:</b> Left-turning vehicles from Somerset Street limit visibility of opposing vehicles.	Medium/High	
RSA Team's Recommendation	Cost	Potential Safety Benefit
Consider installing left-turn arrows from Somerset Street to Easton Avenue north and south. (35)	Low	Medium/High
Consider installing lane reconfiguration with head-to-head left turns. (36)	Low	Medium/High
Conduct turning analysis to evaluate turning movements and potentially revise intersection striping to include head-to-head left-turn lanes.(33)	Low	Medium/High

Issue: Crosswalks (Easton/Somerset)	Safety Risk
<b>Description:</b> The crosswalks do not accommodate pedestrian desire lines.	Medium/Low
<b>Description:</b> Pedestrian accommodations, such as ramps and detectable warning surfaces, are not fully ADA compliant.	Medium



RSA Team's Recommendation	Cost	Potential Safety Benefit
Plan for full ADA compliance by scheduling upgrades of existing ramps and curbs at crosswalks. (3)	Medium	Medium
Consider the installation of ergonomic crosswalks, to provide for natural pedestrian movements. (38) [See diagram below.]	Low	Medium



Issue: Pedestrian Accommodations (Easton/Somerset)	Safety Risk	
<b>Description:</b> Pedestrian buttons are not properly aligned in accordance with ADA requirements.	Medium	
<b>Description:</b> Pedestrian heads are not located in the direct line of sight of pedestrians using the crosswalks.	Low/Medium	
<b>Description:</b> There is a high pedestrian volume at this intersection and it was observed that pedestrians aren't utilizing buttons but crossing with the green light.	Medium/High	
<b>Description:</b> Pedestrian push signage is confusing.	Medium	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
Schedule realignment of the pedestrian buttons to conform to 2009 MUTCD requirements. (20)	Low	Medium/Low
Review the alignment of the pedestrian heads with the crosswalks and sidewalks. (21)	Low	Medium/Low
Evaluate the benefit of revising signal timing to operate on fixed time or pedestrian recall, and adjust as feasible. (39)	Low	Medium/High
Push button signage should be upgraded to conform to the 2009 MUTCD. (37)	Low	Medium

Issue: Signage (Easton/Somerset)	Safety Risk	
<b>Description:</b> The “NO TURN ON RED” sign on westbound Somerset Street is not visible from the stop bar.	Medium/High	
<b>Description:</b> The “NO TURN ON RED” sign on northbound Easton Avenue is missing.	Medium/High	
<b>Description:</b> There are missing stop bars in the intersection.	Medium	
RSA Team’s Recommendation	Cost	Potential Safety Benefit
Ensure that the “NO TURN ON RED” sign is properly aligned with the stop bar in the northeast corner on Somerset Street; add a supplemental sign on the far side of the intersection. (40)	Low	Medium/High
If appropriate, replace the “NO TURN ON RED” sign. (41)	Low	Medium
Ensure that the missing stop bar and other roadway markings are replaced. (42)	Low	Medium

Issue: Lighting (Easton/Somerset)	Safety Risk	
<b>Description:</b> Lighting is inconsistent and not uniform at Easton Avenue and Somerset Street, and may not address the nighttime visibility needs of both pedestrians and vehicles.	Medium/High	
RSA Team’s Recommendation	Cost	Potential Safety Benefit
Professional staff should conduct a formal engineering review of existing lighting conditions to evaluate where both vehicle and pedestrian level lighting can be enhanced. (5)	Medium	Medium/High

Issue: Sight Distance (Easton/Somerset)	Safety Risk	
<b>Description:</b> Cars were parked close to the intersection, obstructing the sight distance of pedestrians in the intersection.	Medium/High	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
Consider installing a "NO PARKING" sign, roadway markings, and/or stanchions to delineate parking/no parking areas. (43)	Low	Medium/High

## Somerset Street & College Avenue

### RSA Team Findings

The following section details the specific findings and recommendations made by the RSA team. All recommendations and designs should be thoroughly evaluated by the roadway owner and/or a professional engineer for conformance to codes, standards, and best practices.

Issue: Lighting (Somerset/College)	Safety Risk	
<b>Description:</b> Lighting was inconsistent and not uniform at Somerset Street and College Avenue and may not address the nighttime visibility needs of both pedestrians and vehicles.	Medium/High	
RSA Team's Recommendation	Cost	Potential Safety Benefit
Professional staff should conduct a formal engineering review of existing lighting conditions to evaluate where both vehicle and pedestrian level lighting can be enhanced. (5)	Medium	Medium/High


Issue: Pedestrians (Somerset/College)	Safety Risk	
<b>Description:</b> The eastern crosswalk across Somerset Street at College Avenue, which is the main access from Rutgers University to the train station, is too narrow for the volume of pedestrians.	Low	
<b>Description:</b> The visibility of the crosswalk from College Avenue across Somerset Street is limited.	Medium/High	
<b>Description:</b> The crosswalk is long and could be made more pedestrian friendly.	Medium	
RSA Team's Recommendation	Cost	Potential Safety Benefit
Widening the crosswalk could more easily accommodate the pedestrian volume. (44)	Low	Low
Consider the installation of a pedestrian crossing sign. (45)	Low	Medium/High
Consider the installation of (curbed or painted) bulb-outs at both corners of College Avenue and on Somerset Street. (46) [See drawing on following page.]	Low-Painted; Medium-Curbed	Medium/High




<b>Issue: Traffic Operations (Somerset/College)</b>	<b>Safety Risk</b>
<b>Description:</b> Buses making a left turn from College Avenue onto Somerset Street are forced into the “Right Turn Only” lane on College Avenue	Medium/Low



RSA Team’s Recommendation	Cost	Potential Safety Benefit
Removing the lane striping and providing a single lane allowing for both right and left turns would accommodate the wide left turns. (47) [See drawing below.]	Low	Medium
Consider the installation of (curbed or painted) bulb-outs at both corners of College Avenue and on Somerset Street (46) [See drawing below.]	Low-Painted; Medium-Curbed	Medium/High




Issue: Passenger Drop-Off (Somerset/College)	Safety Risk	
<b>Description:</b> The unofficial drop-off and pick-up area on Somerset Street is congested.	Medium/Low	
RSA Team's Recommendation	Cost	Potential Safety Benefit
Evaluate installing an official "Kiss-and-Ride" drop-off/pick-up zone on Somerset Street at the Gateway sidewalk (to the train station) with appropriate signage and roadway markings. (48)	Low	Medium/Low

Issue: Pavement (Somerset/College)	Safety Risk	
<b>Description:</b> The pavement is in poor condition throughout the intersection.	Low	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
Consider repaving the intersection. (49)	Medium	Medium/Low

## Somerset Street & Wall Street

### RSA Team Findings

The following section details the specific findings and recommendations made by the RSA team. All recommendations and designs should be thoroughly evaluated by the roadway owner and/or a professional engineer for conformance to codes, standards and best practices.



Issue: Bus Stop (Somerset/Wall)	Safety Risk	
<p><b>Description:</b> Because this is a bus stop for numerous routes for NJ Transit, Rutgers, County buses, and city shuttles, there is significant passenger confusion.</p>	<p>Low</p>	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
<p>Consider adding signage that includes maps of the various bus routes bus schedule. (50)</p>	<p>Low</p>	<p>Low</p>


Issue: Pedestrian Accommodations (Somerset/Wall)	Safety Risk	
<b>Description:</b> Pedestrian accommodations, such as ramps and detectable warning surfaces, are not fully ADA compliant at Somerset and Wall Streets.	Medium	
RSA Team's Recommendation	Cost	Potential Safety Benefit
Plan for full ADA compliance by scheduling upgrades to existing ramps and curbs at the crosswalks. (3)	Medium	Medium

## Somerset Street & George Street (CR 672)

### RSA Team Findings

The following section details the specific findings and recommendations made by the RSA team. All recommendations and designs should be thoroughly evaluated by the roadway owner and/or a professional engineer for conformance to codes, standards, and best practices.

Issue: Turning Angle (Somerset/George)	Safety Risk	
<p><b>Description:</b> Some buses making a right turn from Somerset Street to George Street have difficulty, due to the sharp intersection between the two roadways.</p>	High	
<p>Vehicles use the bus stop area on Somerset Street as a right turn lane.</p>	Medium	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
<p>Conduct a thorough evaluation to improve the geometry of the intersection, realigning Somerset Street so that it makes a right angle with George Street. (51)</p>	High	High
<p>Evaluate if installation of a traffic signal is warranted to better accommodate turning buses and vehicles into the parking deck. (52)</p>	High	High
<p>Consider hatching the bus stop area to prohibit vehicles from turning right at the same time that a bus is making a wide right turn. (53) [See diagram on page 62.]</p>	Low	Medium/High
<p>Consider installing a blinking yellow light on northbound George Street, prior to the intersection, alerting motorists to use caution. (54)</p>	High	High

Issue: Sight Distance (Somerset/George)	Safety Risk	
<b>Description:</b> Parked vehicles on southbound George Street limit the sight distance of oncoming traffic from Somerset Street.	Medium/High	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
Consider limiting parking on George Street, north of the intersection. (55)	Low	Medium/High



Issue: Parking Deck (Somerset/George)	Safety Risk
<b>Description:</b> Some drivers have difficulty making a left turn into the J & J parking deck at 410 George Street.	Medium-Low
<b>Description:</b> The existing crosswalk across George Street (south of the intersection and bridge) is very long.	Low



RSA Team's Recommendation	Cost	Potential Safety Benefit
Evaluate if installation of a traffic signal is warranted to better accommodate turning buses and vehicles turning into the parking deck. (52)	High	High
Consider adding a left-turn lane on George Street northbound (for the parking deck). (56)	Low	Medium
Northbound George Street (south of the railroad bridge) narrows to no shoulder just past the crosswalk. Consider revising the narrowing to a location prior to the crosswalk to shorten the crosswalk length. (63)	High	Low/Medium




Issue: Crosswalk (Somerset/George)	Safety Risk
<b>Description:</b> The crosswalk in the northwest corner is not clearly delineated because of the wide driveway entrance to Rutgers University, nor is it ADA compliant.	Medium-Low
<b>Description:</b> Pedestrian accommodations, such as ramps and detectable warning surfaces, are not fully ADA compliant at the intersection of Somerset and George Streets.	Medium
<b>Description:</b> There is no marked crosswalk across George Street north of the intersection.	Medium
<b>Description:</b> The crosswalk across Somerset Street is very long.	Medium/High




RSA Team's Recommendation	Cost	Potential Safety Benefit
The northwest corner could be improved for pedestrians, possibly with additional striping and continuation of the sidewalk from Somerset Street across the Rutgers driveway. (58) [See diagram on page 62.]	Low	Medium
Plan for full ADA compliance by scheduling upgrades to existing ramps and curbs at crosswalks. (3)	Medium	Medium
Consider the installation of bulb-outs (curbed or painted) at the intersection in addition to a crosswalk across the Rutgers driveway. (59) [See diagram on page 62.]	Low-Painted; Medium-Curbed	Medium/High
The addition of a marked crosswalk at George Street north of the intersection would alert drivers to possible pedestrian activity. (60) [See diagram on page 62.]	Low	Medium/High

Consider the installation of bulb-outs (curbed or painted) at a proposed crosswalk across George Street. (61) [See diagram below.]	Low-Painted; Medium-Curbed	Medium/High
Consider the installation of a visibly differentiated mountable refuge island across Somerset Street. (62) [See diagram below.]	Low-Painted; Medium-Mountable	Medium/High



Issue: Lighting (Somerset/George)	Safety Risk	
<b>Description:</b> Lighting at the intersection was inconsistent and not uniform, especially under the railroad bridge, and may not address the nighttime visibility needs of both pedestrians and vehicles.	Medium/High	
RSA Team's Recommendation	Cost	Potential Safety Benefit
Professional staff should conduct a formal engineering review of existing lighting conditions to evaluate where both vehicle and pedestrian level lighting can be enhanced. (5)	Medium	Medium/High

Issue: Signage (Somerset/George)	Safety Risk	
<b>Description:</b> The stop sign lacks retro-reflectivity.	Medium	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
Plan on replacing the stop sign to conform to MUTCD standards. (64)	Low	Medium/High


## George Street (CR 672/171) & Albany Street (Route 27)


---

### ***RSA Team Findings***

The following section details the specific findings and recommendations made by the RSA team. All recommendations and designs should be thoroughly evaluated by the roadway owner and/or a professional engineer for conformance to codes, standards, and best practices.

Issue: Pedestrian Heads (George/Albany)	Safety Risk	
<b>Description:</b> Pedestrian heads are not located in the direct line of sight of pedestrians using the crosswalks.	Low	
<b>Description:</b> Right-turning vehicles obstruct clear sight of pedestrian signal heads.	Medium	
<b>Description:</b> Some of the pedestrian heads are not functioning.	High	
RSA Team's Recommendation	Cost	Potential Safety Benefit
Review and adjust the alignment of the pedestrian heads with the crosswalks and sidewalks. (21)	Medium/Low	Medium/Low
Consider installing countdown pedestrian heads in the median refuge. (65)	High	High
Repair the pedestrian heads. (66)	Low	Medium/High

Issue: Pedestrian Accommodations (George/Albany)	Safety Risk	
<b>Description:</b> Pedestrians were observed crossing George Street in line with the sidewalk, which is not aligned with the crosswalk.	Low	
<b>Description:</b> Pedestrian accommodations, such as ramps and detectable warning surfaces, are not fully ADA compliant.	Medium/Low	
<b>Description:</b> Some of the bricks in the sidewalk have settled and may cause a tripping hazard.	Medium/Low	
<b>Description:</b> A significant number of people utilize the bus stops.	Medium	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
Pedestrians could be better accommodated by aligning the crosswalks with the sidewalks. (67)	Low	Medium
Plan for full ADA compliance by scheduling upgrades to existing ramps and curbs at crosswalks. (3)	Medium/Low	Medium
Regular maintenance should include repairing the bricks where they have settled. (68)	Low	Medium/High
Consider the installation of bus shelters. (69)	<b>Note:</b> NJ Transit will install bus shelters at no cost, conditional with the city maintenance and J&J easement.	Medium

Issue: Signage (George/Albany)	Safety Risk	
<b>Description:</b> Left-turn prohibition is not clear to drivers because of missing and faded signage.	Medium/High	
<b>Description:</b> There is an unused broken pole in the southeast corner of the intersection.	Low	
		
RSA Team's Recommendation	Cost	Potential Safety Benefit
Replace all "NO LEFT TURN" signage where necessary. (70)	Low	High
Remove the unused broken pole at the southeast corner. (71)	Low	Low/Medium

Issue: Traffic Operations (George/Albany)	Safety Risk	
<b>Description:</b> Cars often drive over the curb at the southwest corner.	Low	
<b>Description:</b> There is excessive queuing from left-turn volume on southbound George Street to eastbound Albany Street.	Medium	
RSA Team's Recommendation	Cost	Potential Safety Benefit
Investigate why vehicles are striking the curb in the southwest corner and consider revising geometry. (72)	High	Low
Evaluate the installation of signage diverting traffic from George Street to Johnson Drive for the left turn onto Albany Street. (73)	Low	Medium/High
Consider the installation of lead- or lag-left signal phasing. (74)	Medium/High	Medium/High



Issue: Bicycles (George/Albany)		Safety Risk	
<b>Description:</b> There are no accommodations for bicycle travel in the area around the George and Albany Streets intersection.		Medium/High	
			
RSA Team's Recommendation		Cost	Potential Safety Benefit
Professional engineering staff should do a full evaluation of bicycle travel in the area around the train station. (8)		Low	Medium/High
Support improvements to the proposed New Brunswick Bike Lane project within the intersection. (76) See bikeway map: <a href="http://thecityofnewbrunswick.org/planninganddevelopment/files/Bike-Lanes-2012-20131.pdf">http://thecityofnewbrunswick.org/planninganddevelopment/files/Bike-Lanes-2012-20131.pdf</a>		Low	Medium

Issue: Sight Distance (George/Albany)		Safety Risk	
<b>Description:</b> When the loading area on the southeast corner is full, trucks extend past the designated area, sometimes blocking the crosswalk and creating a traffic hazard due to impaired sight distance.		Medium/High	
RSA Team's Recommendation		Cost	Potential Safety Benefit
Consider providing additional loading zone areas for trucks. (75)		Low	Medium/High

## Implementing Recommendations

---

The RSA team's recommendations detailed in this report should improve the safety of the seven intersections in the vicinity of the New Brunswick train station. Most of the roadway recommendations fall under Middlesex County's jurisdiction. The intersections of Easton Avenue & Wall Street and Somerset & Wall Streets are under the jurisdiction of the City of New Brunswick. Any potential improvements generated as a result of this report would be led by either the County of Middlesex or the City of New Brunswick.

Many of the recommendations contained within this report—such as maintaining signs, pavement conditions and roadway markings—can be implemented through routine maintenance, while others will take more time and investment. Maximizing limited resources and developing partnerships can help to extend the impact of safety efforts. Rutgers' TSRC can provide support to municipalities and counties in identifying partnership opportunities. The North Jersey Transportation Planning Authority (NJTPA) can also assist by providing crash data and/or capacity analysis.

Some of the recommendations may require sizable capital investment to ensure a long-term safety benefit. It is understood that larger projects may require funding assistance from non-county and non-municipal sources. Potential funding sources are provided in the section following the summary of recommendations.

In addition to physical improvements, a combined effort of public education and enforcement is necessary to make these intersections safer for all roadway users. The New Jersey Division of Highway Traffic Safety and its community partners—including the Transportation Management Associations, police agencies, and nonprofits—fund and/or provide educational programs addressing pedestrian and bicycle safety and safe driving practices. A variety of outreach programs conducted in school and community-based settings, as well as informational materials, are available and can be tapped to address safety in the area addressed by this RSA.

Enforcement of no-parking zones, posted speed limits, and pedestrian right-of-way and jaywalking, are proven to reduce crashes and help improve the safety practices of all roadway users. Officers may also hand out pamphlets during routine traffic stops to educate motorists about traffic laws as well as conduct pedestrian decoy enforcement activities (Cops in the Crosswalk program) to engage both motorists and pedestrians.

## **Recommendations**

The following section summarizes the recommendations detailed in the RSA team finding section. They are listed by jurisdiction as well as by the cost and effort (Long, Medium, and Short Term) required for implementation. (It should be noted that these designations are both subjective and fluid.

The following intersections are under the jurisdiction of Middlesex County:  
(Recommendations related to parking and signage are under the jurisdiction of the City of New Brunswick.)

- Easton Avenue (CR 514) & Albany Street (Route 27)
- Easton Avenue (CR 514) & Wall /Little Albany Street
- Easton Avenue (CR 514) & Somerset Street
- Somerset & George Streets (CR 672)
- George (CR 672/171) & Albany Streets (Route 27)

The following intersections are under the jurisdiction of the City of New Brunswick:

- Somerset Street & College Avenue
- Somerset & Wall Streets

## Middlesex County

---

### *Long Term*

#### Traffic Signals

- 52 **Somerset & George:** Evaluate if the installation of a traffic signal is warranted to better accommodate buses and vehicles turning into the J & J parking deck.
- 54 **Somerset & George:** Consider installing a blinking yellow light on northbound George Street prior to the intersection, alerting motorists to use caution.
- 65 **George & Albany:** Consider installing a countdown pedestrian head in the median refuge.
- 74 **George & Albany:** Consider the installation of lead– or lag–left signal phasing.

#### Geometry

- 51 **Somerset & George:** Conduct a thorough evaluation to improve the geometry of the intersection, realigning Somerset Street so that it makes a right angle with George Street.
- 63 **Somerset & George:** Northbound George Street (south of the railroad bridge) narrows to no shoulder just past the crosswalk. Consider revising the narrowing to a location prior to the crosswalk to shorten the crosswalk length.
- 72 **George & Albany:** Investigate why vehicles are striking the curb in the southwest corner and consider revising the geometry.

### *Medium Term*

#### Pedestrians

- 3 **Corridorwide:** Plan for full ADA compliance by scheduling upgrades of existing ramps and curbs at crosswalks.
- 4 **Corridorwide:** Improve appearance of pedestrian crossings by shortening them to encourage pedestrians to cross at marked crosswalks.
- 30 **Easton & Wall:** Consider installation of bulb-outs (painted, curbed, or stanchions), which would shorten the crosswalk.
- 58 **Somerset & George:** The northwest corner could be improved for pedestrians, possibly with additional striping and by delineating the continuation of the sidewalk from Somerset Street across the Rutgers driveway.
- 59 **Somerset & George:** Consider the installation of bulb-outs (curbed or painted) at the intersection in addition to a crosswalk across the Rutgers driveway.
- 61 **Somerset & George:** Consider the installation of bulb-outs (curbed or painted) at a proposed crosswalk at George Street.
- 62 **Somerset & George:** Consider the installation of a visibly differentiated mountable refuge island at Somerset Street.

### Traffic Operations

- 35 **Easton & Somerset:** Consider installing left-turn arrows from Somerset Street to Easton Avenue north and south.

### Bridge Conditions

- 26 **Easton & Albany, Easton & Wall:** Request that Amtrak make appropriate repairs to the bridge to alleviate the dripping water.

### Pavement Conditions

- 11 **Easton & Albany:** Identify locations of raised manhole covers and consider resetting the manhole covers to be flush with pavement.

### Traffic Signals

- 16 **Albany & Easton:** Consider rephasing signal timing so that the walk signal across easterly Albany Street comes before the left turn from southbound Easton Avenue to northbound Albany Street.

## *Short Term*

### Roadway Markings

- 1 **Corridorwide:** Regular maintenance should ensure that the roadway markings are clearly visible to pedestrians and vehicles.
- 2 **Corridorwide:** Installation of retro-reflective pavement markings would significantly increase visibility.
- 25 **Easton & Albany:** Consider the addition of dotted lane line extension pavement markings, delineating the dual left-turning movement from southbound Easton Avenue to northbound Albany Street.
- 27 **Easton & Wall:** Ensure that the missing crosswalk at Little Albany Street is clearly marked.
- 33 **Easton & Somerset:** Conduct a turning analysis to evaluate turning movements and potentially revise intersection striping to include head-to-head left-turn lanes.
- 42 **Easton & Somerset:** Ensure that the missing stop bar and other roadway markings are replaced.

### Traffic Signal

- 16 **Albany & Easton:** Consider rephasing signal timing so that the walk signal across easterly Albany Street comes before the left turn from southbound Easton Avenue to northbound Albany Street.
- 39 **Easton & Somerset:** Evaluate the benefit of revising signal timing to operate on fixed time or pedestrian recall, and adjust as feasible.

### Signage

- 6 **Corridorwide:** Professional engineering staff should conduct a thorough evaluation of existing and required signage to reduce the amount of signage in the intersection and decrease sign clutter.
- 31 **Easton & Wall:** Consider installing a “NO LEFT TURN” sign in the far-left corner (for traffic exiting Wall Street onto Easton Avenue southbound) in conformance to the MUTCD.

- 34 **Easton & Somerset:** Consider prohibiting right turns on red and place MUTCD signage on all four corners.
- 40 **Easton & Somerset:** Ensure that the “NO TURN ON RED” sign is properly aligned with the stop bar in the northeast corner on Somerset Street; add a supplemental sign on the far side of the intersection.
- 41 **Easton & Somerset:** If appropriate, replace the “NO TURN ON RED” sign.
- 70 **George & Albany:** Replace all “NO LEFT TURN” signage, where necessary.
- 71 **George & Albany:** Remove the unused broken pole at the southeast corner.

**Traffic Operations**

- 8 **Corridorwide:** Professional engineering staff should do a full evaluation of bicycle travel in the area around the train station.
- 24 **Easton & Albany:** Evaluate an alternative to the existing bus stop by revising the striping on northbound Albany Street to increase the width on southbound Albany Street and allow the relocation of the bus stop just past the intersection, after the ramp from southbound Easton Avenue.
- 34 **Easton & Somerset:** Consider the installation of a right-turn-on-red prohibition with a “NO TURN ON RED” sign in all four corners.
- 36 **Easton & Somerset:** Consider installing lane reconfiguration with head-to-head left turns.
- 73 **George & Albany:** Evaluate the installation of signage diverting traffic from George Street to Johnson Drive for the left turn onto Albany Street.

**Pedestrians**

- 9 **Easton & Albany:** Consider removing the unused broken pole in the island curb ramp (from southbound Easton Avenue to Albany Street).
- 12 **Easton & Albany:** Consider installation of a marked crosswalk across the “Kiss-and-Ride” driveway on southbound Albany Street.
- 13 **Easton & Albany:** Evaluate unofficial crossing locations in the median on Albany Street and consolidate or eliminate them, if possible.
- 14 **Easton & Albany:** Consider resetting or relocating the junction box
- 15 **Easton & Albany:** Ensure crossing times are compliant with the 2009 edition of the MUTCD.
- 17 **Easton & Albany:** Evaluate adding an all-red, all-way pedestrian crossing at the intersection.
- 18 **Easton & Albany:** Plan to realign and/or limit visibility of the walk signal so pedestrians do not receive conflicting information.
- 19 **Easton & Albany:** To accommodate the high pedestrian volume, consider operating the signal in fixed time or utilizing pedestrian recall.
- 20 **Easton & Albany, Easton & Somerset:** Schedule realignment of the pedestrian buttons to conform to the 2009 edition of the MUTCD.
- 21 **Easton & Albany, Easton & Somerset, George & Albany:** Review and adjust the alignment of the pedestrian heads with the crosswalks and sidewalks.

- 28 **Easton & Wall:** Installation of a marked crosswalk across Easton Avenue south of the intersection would increase the safety of pedestrians who are crossing at this location and alert motorists to a pedestrian crossing.
- 30 **Easton & Wall:** Consider installation of bulb-outs (painted, curbed, or stanchions) to shorten the crosswalk.
- 32 **Easton & Wall:** The broken pole on southbound Easton Avenue, north of Little Albany Street, should be removed.
- 38 **Easton & Somerset:** Consider the installation of ergonomic crosswalks to provide for the natural pedestrians movements.
- 59 **Somerset & George:** Consider the installation of bulb-outs (painted) at the intersection in addition to a crosswalk at the Rutgers driveway.
- 60 **Somerset & George:** The addition of a marked crosswalk at George Street north of the intersection would alert drivers for possible pedestrian activity. (See drawing in Appendix E.)
- 61 **Somerset & George:** Consider the installation of bulb-outs (curbed or painted) at a proposed crosswalk at George Street.
- 62 **Somerset & George:** Consider the installation of a visibly differentiated mountable refuge island at Somerset Street.
- 66 **George & Albany:** Schedule repair of the pedestrian heads.
- 67 **George & Albany:** Pedestrians could be better accommodated by aligning the crosswalks with the sidewalks.



### *Long Term*

#### **Bus**

- 69 **George & Albany:** Consider the installation of bus shelters.

### *Medium Term*

#### **Pedestrians**

- 3 **Corridorwide:** Plan for full ADA compliance by scheduling upgrades to existing ramps and curbs at the crosswalks.
- 4 **Corridorwide:** Improve pedestrian crossings to encourage pedestrians to cross in marked crosswalks.
- 46 **Somerset & College:** Consider the installation of (curbed or painted) bulb-outs at both corners of College Avenue and on Somerset Street.

#### **Lighting**

- 5 **Corridor Wide:** Professional staff should conduct a formal engineering review of existing lighting conditions to evaluate where both vehicle and pedestrian level lighting can be enhanced.

#### **Bridge Conditions**

- 26 **Easton & Albany, Easton & Wall:** Request that Amtrak make appropriate repairs to the bridge to alleviate the dripping water.

#### **Pavement Conditions**

- 49 **Somerset & College:** Consider repaving the intersection.

### *Short Term*

#### **Roadway Markings**

- 1 **Corridorwide:** Regular maintenance should keep the roadway markings clearly visible to pedestrians and vehicles.
- 2 **Corridorwide:** Installation of retro-reflective pavement markings would significantly increase visibility.
- 29 **Easton & Wall:** Pavement markings would more clearly delineate the “NO PARKING” zone.
- 42 **Easton & Somerset:** Ensure that the missing stop bar and other roadway markings are replaced.
- 43 **Easton & Somerset:** Consider installing a “NO PARKING” sign, roadway markings, and/or stanchions to delineate parking/no parking areas.
- 47 **Somerset & College:** Removing the lane striping and providing a single lane allowing for both right and left turns would accommodate the wide left turns.
- 53 **Somerset & George:** Consider hatching the bus stop area to prohibit vehicles from turning right at the same time that a bus is making a wide right turn.

### Signage

- 6 **Corridorwide:** Professional engineering staff should conduct a thorough evaluation of existing and required signage to reduce the amount of signage in the intersection and decrease sign clutter.
- 10 **Easton & Albany, Easton & Wall:** Evaluate creating a dedicated taxi stand and installing signage in the area under the bridge at northbound Easton Avenue.
- 43 **Easton & Somerset:** Consider installing a “NO PARKING” sign, roadway markings, and/or stanchions to delineate parking/no parking areas.
- 45 **Somerset & College:** Consider the installation of a pedestrian crossing sign.
- 50 **Somerset & Wall:** Consider adding signage that includes maps of the various bus routes and bus schedules.
- 64 **Somerset & George:** Replace the stop sign so that it conforms to MUTCD standards.

### Traffic Operations

- 7 **Corridorwide:** Professional engineering staff should conduct a thorough evaluation of the train station traffic, including passenger pick-up and drop-off points and locations for taxi stands.
- 8 **Corridorwide:** Professional engineering staff should do a full evaluation of bicycle travel in the area around the train station to complement the New Brunswick Bike Lane project.
- 10 **Easton & Albany, Easton & Wall:** Evaluate creating a dedicated taxi stand and installing signage in the area under the bridge at northbound Easton Avenue.
- 47 **Somerset & College:** Removing the lane striping and providing a single lane allowing for both right and left turns would accommodate the wide left turns.
- 48 **Somerset & College:** Evaluate installing an official “Kiss-and-Ride” drop-off/pick-up zone on Somerset Street at the Gateway sidewalk (to the train station) with appropriate signage and roadway markings.
- 55 **Somerset & George:** Consider limiting parking on George Street, north of the intersection.
- 56 **Somerset & George:** Consider adding a left-turn lane on northbound George Street (for the parking deck).
- 75 **George & Albany:** Consider providing additional loading zone areas for trucks.

### Pedestrians

- 37 **Easton & Somerset:** Push button signage should be upgraded to conform to the 2009 edition of the MUTCD.
- 44 **Somerset & College:** Widening the crosswalk could more easily accommodate the pedestrian volume.
- 46 **Somerset & College:** Consider the installation of (curbed or painted) bulb-outs at both corners of College Avenue and on Somerset Street.
- 68 **George & Albany:** Regular maintenance should include repairing the bricks where they have settled.

### Bicycles

- 22 **Easton & Albany:** Consider the installation of additional bicycle parking.
- 76 **George & Albany:** Support improvements to the proposed New Brunswick Bike Lane project within the intersection.

## Potential Funding Sources

---

In this economy, budget constraints may hamper the implementation of some of these recommendations. Finding alternative funding sources is critical for ensuring investment in safety improvements that would benefit all roadway users.

### Local Funding Sources:

#### **Roadway Owner's Maintenance and Operation Budget:**

Existing funds from local and county sources, as appropriate, which are allocated for investment in maintenance and operational activity, can be used to implement the recommendations outlined in this report. The manager of these funds who understands the full budget picture should be consulted.

### State Funding Sources:

#### **LOCAL AID**

##### **Contact:**

**NJDOT Local Aid District 3 (Hunterdon, Mercer, Middlesex, Monmouth, Ocean, Somerset)**  
District 3, Bureau of Local Aid  
PO Box 600  
Trenton, NJ 08625-0600  
Phone: 732-625-4290  
Fax: 732-625-4292

##### **MUNICIPAL AID/URBAN AID PROGRAM (NJDOT Local Aid):**

<http://www.state.nj.us/transportation/business/localaid/municaid.shtm>

This program has been a significant resource for municipalities in funding local transportation projects. All municipalities are eligible. NJDOT continues to encourage municipalities to consider using the Municipal Aid Program to fund projects such as resurfacing, rehabilitation, or reconstruction and signalization.

##### **LOCAL AID INFRASTRUCTURE FUND (Discretionary Aid):**

<http://www.state.nj.us/transportation/business/localaid/descrfunding.shtm>

Subject to funding appropriation, a discretionary fund is established to address emergencies and regional needs throughout the state. Any county or municipality may apply at any time. These projects are approved at the discretion of the NJDOT commissioner. Payment of project costs is the same as the Municipal Aid Program. Under this program a county or municipality may also apply for funding for local pedestrian safety and bikeway projects.

**SAFE STREETS TO TRANSIT (SSTT):**

<http://www.state.nj.us/transportation/business/localaid/safe.shtm>

This program provides funding to counties and municipalities to improve access to transit facilities and all modes of public transportation. The objectives of the SSTT program are:

- To improve the overall safety and accessibility for mass transit riders walking to transit facilities
- To encourage mass transit users to walk to transit stations
- To facilitate the implementation of projects and activities that will improve safety in the vicinity of transit facilities (approximately one-half mile for pedestrian improvements)

**HIGHWAY SAFETY FUND (Safe Corridors):**

The Safe Corridors grant program targets resources to segments of highways that have a history of high crash rates. Grants are supported by fines that are doubled in designated Safe Corridors for a variety of moving violations, including speeding. FY12 Safe Corridors funding is being allocated based on crash data, with higher amounts of funding going to areas demonstrating the greatest need for continued enhanced enforcement measures. The link to a website is still in development.

**Contact:**

Shukri Abuhuzeima  
Supervising Engineer  
NJDOT Local Aid  
Phone: 609-530-4680  
Email: Shukri.Abuhuzeima@dot.state.nj.us

**BIKEWAY:**

<http://www.state.nj.us/transportation/business/localaid/bikewaysf.shtm>

The NJDOT Bikeway grant program provides funds to counties and municipalities to promote bicycling as an alternate mode of transportation. A primary objective of the Bikeway grant program is to support the state's goal of constructing 1,000 new miles of dedicated bike paths.

**TRANSIT VILLAGES:**

<http://www.state.nj.us/transportation/business/localaid/transitvillagef.shtm>

The Transit Village Grant program is designed to assist municipalities that have been formally designated as Transit Villages. These are municipalities that have made a commitment to grow in the area surrounding a transit facility. The facility can service commuter rail, bus, ferry, or light rail. It funds projects within a one-half mile radius of major transit facilities.

**Contact:**

Leroy Gould  
Transit Village Coordinator  
Phone: 609-530-3864  
Email: Leroy.gould@dot.state.nj.us

**NEW JERSEY DEPARTMENT OF COMMUNITY AFFAIRS**

**MAIN STREET NEW JERSEY**

<http://www.nj.gov/dca/divisions/dhcr/offices/msnj.html>

Main Street New Jersey provides selected communities with technical assistance and training for revitalizing historic downtowns. The program helps municipalities improve the economy, appearance, and image of their central business districts through the organization of local citizens and resources.

**Contact:**

Main Street New Jersey  
NJ Department of Community Affairs – Office of Smart Growth  
P.O. Box 204  
Trenton, NJ 08625-0204  
Jef Buehler  
Phone: 609-633-9769  
Email: [jef.buehler@dca.state.nj.us](mailto:jef.buehler@dca.state.nj.us)

**COMMUNITY DEVELOPMENT BLOCK GRANT (CDBG)**

<http://www.nj.gov/dca/divisions/dhcr/offices/cdbg.html>

The Community Development Block Grant program provides funds for economic development, housing rehabilitation, community revitalization, and public facilities designated to benefit people of low and moderate income, to prevent or eliminate slums and blight, or to address recent local needs for which no other source of funding is available.

**Contact:**

New Jersey Department of Community Affairs  
101 South Broad Street  
PO Box 811, 5<sup>TH</sup> Floor  
Trenton, NJ 08625-0800  
Terry Schrider  
Phone: 609-633-6283  
Email: [terence.schrider@dca.state.nj.us](mailto:terence.schrider@dca.state.nj.us)

## **Federal Funding Sources – via NJDOT Office of Local Aid:**

### **Contact (see details under State Funding section):**

NJDOT Local Aid District 3 (Hunterdon, Mercer, Middlesex, Monmouth, Ocean, Somerset)

### **SAFE ROUTES TO SCHOOLS (SRTS):**

<http://www.state.nj.us/transportation/business/localaid/srts.shtm>

The Safe Routes to Schools program is a federally funded program administered by the State Department of Transportation. It provides funds to substantially improve the ability of primary and middle school students to walk and bicycle to school safely.

The purposes of the program are to:

- enable and encourage children, including those with disabilities, to walk and bicycle to school;
- make bicycling and walking to school a safer and more appealing transportation alternative, thereby encouraging a healthy and active lifestyle from an early age;
- facilitate the planning, development, and implementation of projects and activities that will improve safety and reduce traffic, fuel consumption, and air pollution in the vicinity (approximately two miles) of primary and middle schools (grades K–8).

The program establishes two distinct types of funding opportunities: infrastructure projects (the planning, design, and construction of engineering improvements) and noninfrastructure related activities (such as education, enforcement, and encouragement programs).

### **Contact:**

Elise M Bremer-Nei  
Supervising Planner Transportation, NJDOT  
Statewide Planning  
Phone: 609-530-2765  
Email: Elise.Bremer-Nei@dot.state.nj.us

## **via North Jersey Transportation Planning Authority (NJTPA):**

### **Contact:**

North Jersey Transportation Planning Authority  
One Newark Center, 17th Floor  
Newark, NJ 07102  
Phone: 973-639-8400  
Fax: 973-639-1953



#### **LOCAL SAFETY PROGRAM (LSP):**

[http://www.njtpa.org/Project/Devel/local\\_safety/default.aspx](http://www.njtpa.org/Project/Devel/local_safety/default.aspx)

The federally funded Local Safety Program is a component of wider safety planning at the North Jersey Transportation Planning Authority (NJTPA), supporting construction of quick-fix, high-impact safety improvements on county and local roadway facilities in the MPO's 13-county region. Projects supported by this program include new and upgraded traffic signals, signage, pedestrian indications, crosswalks, curb ramps, pavement markings, and other improvements to increase the safety of drivers, bicyclists, and pedestrians.

The Local Safety Program:

- typically addresses NJTPA and/or NJDOT derived high-priority crash locations on county or local roadways;
- supports quick-fix projects, backed with detailed crash data, with minimal or no environmental or cultural resource impacts (eligible for programmatic categorical exclusion from FHWA);
- funds the construction phase of work only; planning, design, and right-of-way acquisition are the responsibility of the sponsor.

#### **LOCAL CMAQ MOBILITY INITIATIVES:**

<http://www.njtpa.org/Project/Mobility/Default.aspx>

The NJTPA has established the CMAQ Local Mobility Initiatives program to promote a variety of initiatives—including ridesharing, transit usage, travel demand management, and traffic mitigation projects—to lessen the level of pollutants and greenhouse gases generated through the use of fossil fuels. Proposals must implement strategies and policies in the Regional Transportation Plan, Plan 2040.

#### **THE HIGH RISK RURAL ROADS PROGRAM (HRRRP)**

[http://www.njtpa.org/Project/Devel/local\\_safety/default.aspx](http://www.njtpa.org/Project/Devel/local_safety/default.aspx)

High Risk Rural Roads Program provides federal funds for construction improvements to address safety problems *only* on roadways that are functionally classified as rural major collector, rural minor collector, or rural local roads *and* have a crash rate that exceeds the statewide average for those functional classes of roadways. Projects supported by this program have included skid-resistant surface treatments, guiderails, reflective pavement markings, rumbles strips and rumble stripes, safety edge, and enhanced and advanced warning signs.

This program funds the construction phase of work only; planning, design, and right-of-way acquisition are the responsibility of the sponsor.

## **LOCAL CONCEPT DEVELOPMENT (LCD) PHASE of the LOCAL CAPITAL PROJECT DELIVERY PROGRAM (LCPD)**

[http://www.njtpa.org/Project/Devel/local\\_capital\\_program/local\\_concept/default.aspx](http://www.njtpa.org/Project/Devel/local_capital_program/local_concept/default.aspx)

The Local Capital Project Delivery Program provides federal funding for priority local projects. The LCD phase involves drafting a well-defined and well-justified purpose and need statement focusing on the primary transportation need to be addressed. The LCD phase elements include, but are not limited to, data collection, coordination, development of a reasonable number of prudent and feasible conceptual alternatives, and investigation of all aspects of a project. Some of the issues may include environmental, right-of-way, access, utilities, design, community involvement, constructability issues at a “planning level of effort,” and address requirements of the NJTPA Congestion Management Process (CMP).

## **SUBREGIONAL STUDIES PROGRAM**

[http://www.njtpa.org/Plan/Subregion/subregional\\_studies/default.aspx](http://www.njtpa.org/Plan/Subregion/subregional_studies/default.aspx)

This is a competitive program that provides two-year grants to individual subregions (counties) or subregional teams. The program is designed to assist subregions in refining and developing transportation improvement strategies included in the NJTPA’s Regional Transportation Plan (RTP). Ultimately, the program aims to generate project concepts ready for further development or implementation consistent with the RTP and/or other transportation planning activities in the region.

## **TRANSPORTATION ALTERNATIVES PROGRAM**

This is new under MAP-21 and is currently under development at the NJDOT.

<http://www.fhwa.dot.gov/map21/guidance/guidetap.cfm>

The Transportation Alternatives Program (TAP) provides funding for programs and projects defined as transportation alternatives, including on- and off-road pedestrian and bicycle facilities, infrastructure projects for improving non-driver access to public transportation and enhanced mobility, community improvement activities, and environmental mitigation; recreational trail program projects; safe routes to school projects; and projects for the planning, design, or construction of boulevards and other roadways largely in the right-of-way of former interstate system routes or other divided highways.

## **Federal Funding Sources – via NJ Division of Highway Traffic Safety:**

<http://www.nj.gov/oag/hts/grants/index.html>

The NJ Division of Highway Traffic Safety offers, on an annual basis, federal grant funding to agencies that wish to undertake behavioral safety programs through education and enforcement activities designed to reduce motor vehicle crashes, injuries, and fatalities on the roadways of New Jersey. Municipal, county, state government, and law enforcement agencies, as well as nonprofit organizations, are encouraged to apply for grant funding to address specific, local traffic safety issues.

**Contact:**

Ed O'Connor, Central Region Supervisor

Phone: 609-633-9048

Email: [Edward.O'Connor@lps.state.nj.us](mailto:Edward.O'Connor@lps.state.nj.us)

# **Appendix A – Raw Crash Data**

---



***Easton Avenue (CR 514) & Albany Street (Route 27)***

CRASH DATE	CRASH TIME	CRASH TYPE	LIGHT CONDITION	SEVERITY	SURFACE CONDITION	TOTAL INJURED	TOTAL PEDESTRIANS INVOLVED
2/2/2007	11:01 AM	Struck Parked Vehicle	Daylight	Property Damage	Dry	0	0
2/6/2007	5:20 PM	Left Turn / U-Turn	Dusk	Property Damage	Dry	0	0
2/7/2007	3:31 PM	Same Direction – Rear End	Dark (Street Lights On /Continuous)	Property Damage	Dry	1	0
2/24/2007	9:22 AM	Same Direction – Side Swipe	Dark (Street Lights On /On /Continuous)	Property Damage	Dry	0	0
4/23/2007	9:53 PM	Pedalcyclist	Dark (Street Lights On /Continuous)	Injury	Dry	0	0
4/23/2007	10:08 PM	Fixed Object	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	0
5/23/2007	8:45 PM	Same Direction – Rear End	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	0
6/28/2007	7:17 PM	Same Direction – Side Swipe	Daylight	Property Damage	Wet	0	0
7/8/2007	6:16 PM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	0
8/12/2007	1:10 PM	Same Direction – Rear End	Daylight	Property Damage	Dry	0	0
9/11/2007	8:06 PM	Same Direction – Side Swipe	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	0
9/11/2007	4:46 PM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	0
10/26/2007	4:31 PM	Same Direction – Side Swipe	Daylight	Property Damage	Wet	0	0
11/2/2007	7:50 AM	Same Direction – Rear End	Daylight	Property Damage	Dry	0	0
11/26/2007	8:25 PM	Right Angle	Dark (Street Lights On /Spot)	Property Damage	Wet	0	0
12/26/2007	2:06 PM	Same Direction – Rear End	Daylight	Property Damage	Dry	0	0
2/12/2008	3:45 PM	Same Direction – Rear End	Daylight	Property Damage	Snowy	0	0
3/8/2008	11:17 AM	Fixed Object	Daylight	Property Damage	Wet	0	0
4/18/2008	4:39 PM	Struck Parked Vehicle	Daylight	Property Damage	Dry	1	0
4/24/2008	10:28 AM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	0

CRASH DATE	CRASH TIME	CRASH TYPE	LIGHT CONDITION	SEVERITY	SURFACE CONDITION	TOTAL INJURED	TOTAL PEDESTRIANS INVOLVED
5/13/2008	12:01 PM	Backing	Daylight	Property Damage	Dry	0	0
7/15/2008	5:51 PM	Same Direction – Side Swipe	Daylight		Dry	0	0
7/20/2008	5:58 PM	Same Direction – Rear End	Daylight		Dry	0	0
8/14/2008	12:15 PM	Right Angle	Daylight	Injury	Dry	0	0
8/23/2008	9:32 AM	Same Direction – Rear End	Daylight		Dry	0	0
10/12/2008	2:01 AM	Fixed Object	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	0
12/11/2008	9:42 AM	Struck Parked Vehicle	Daylight	Property Damage	Wet	0	0
1/30/2009	4:37 PM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	0
2/18/2009	2:43 PM	Pedestrian	Daylight	Injury	Wet	1	1
4/20/2009	8:22 AM	Pedestrian	Daylight	Injury	Dry	1	2
6/17/2009	2:34 PM	Right Angle	Daylight	Property Damage	Unknown	0	0
7/29/2009	9:54 AM	Pedestrian	Daylight	Injury	Dry	0	0
8/12/2009	5:33 PM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	1	2
9/13/2009	3:12 AM	Pedestrian	Dark (Street Lights On /Continuous)	Injury	Wet	0	0
9/29/2009	9:55 PM	Same Direction – Rear End	Dark (Street Lights On /Continuous)	Property Damage	Dry	1	1
10/16/2009	5:32 PM	Same Direction – Side Swipe	Daylight		Wet	0	0
11/14/2009	8:21 PM	Same Direction – Rear End	Dark (Street Lights On /Continuous)	Property Damage	Wet	0	0



***Easton Avenue (CR 514) & Wall Street/Little Albany Street***

CRASH DATE	CRASH TIME	CRASH TYPE	LIGHT CONDITION	SEVERITY	SURFACE CONDITION	TOTAL INJURED	TOTAL PEDESTRIANS INVOLVED
2/25/2007	9:08 PM	Right Angle	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	0
5/14/2007	12:50 PM	Same Direction – Rear End	Daylight	Property Damage	Dry	0	0
8/28/2007	2:44 PM	Struck Parked Vehicle	Daylight	Property Damage	Dry	0	0
11/14/2007	8:03 AM	Right Angle	Daylight	Injury	Icy	0	0
12/2/2007	7:32 AM	Same Direction – Rear End	Daylight			0	0
2/13/2008	7:16 AM	Pedestrian	Daylight		Dry	0	0
2/22/2008	1:35 AM	Same Direction – Rear End	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	0
3/5/2008	12:31 PM	Struck Parked Vehicle	Daylight		Snowy	0	0
5/22/2008	6:42 PM	Same Direction – Side Swipe	Daylight		Dry	0	0
5/29/2008	2:31 PM	Fixed Object	Daylight		Dry	0	0
11/12/2008	1:15 PM	Right Angle	Daylight	Property Damage	Dry	0	0
12/18/2008	2:54 PM	Right Angle	Daylight		Wet	1	1
2/24/2009	6:56 AM	Same Direction – Side Swipe	Daylight		Dry	0	0
3/23/2009	2:31 PM	Left Turn / U-Turn	Daylight		Dry	0	0
4/6/2009	1:07 PM	Same Direction – Rear End	Daylight	Injury	Wet	1	0
7/7/2009	1:01 PM	Struck Parked Vehicle	Daylight		Dry	0	0
7/14/2009	1:58 PM	Same Direction – Rear End	Daylight	Injury	Dry	1	0
10/20/2009	4:01 PM	Pedalcyclist	Daylight	Injury	Dry	1	0
11/4/2009	7:22 AM	Right Angle	Daylight		Dry	0	0

### *Easton Avenue (CR 514) & Somerset Street*

CRASH DATE	CRASH TIME	CRASH TYPE	LIGHT CONDITION	SEVERITY	SURFACE CONDITION	TOTAL INJURED	TOTAL VEHICLES INVOLVED
1/15/2007	12:12 PM	Backing	Daylight	Property Damage	Wet	1	2
1/19/2007	6:44 PM	Same Direction – Rear End	Dark (Street Lights On /Continuous)	Injury	Dry	0	2
2/2/2007	10:43 PM	Left Turn / U-Turn	Dark (Street Lights On /Continuous)	Injury	Wet	0	2
2/28/2007	6:06 AM	Pedestrian	Dawn	Injury	Dry	0	2
3/31/2007	4:07 PM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	3
5/8/2007	9:29 AM	Struck Parked Vehicle	Daylight	Property Damage	Dry	0	3
7/5/2007	5:36 PM	Same Direction – Side Swipe	Daylight	Property Damage	Wet	0	2
7/27/2007	6:16 PM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	2
8/2/2007	12:57 AM	Struck Parked Vehicle	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	4
8/8/2007	5:02 PM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	2
8/12/2007	4:07 PM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	2
9/8/2007	1:11 AM	Opposite Direction – Side Swipe	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	2
10/4/2007	4:03 PM	Same Direction – Rear End	Daylight	Property Damage	Dry	0	2
10/7/2007	2:46 PM	Backing	Daylight	Property Damage	Dry	0	2
10/8/2007	10:17 AM	Struck Parked Vehicle	Daylight	Property Damage	Dry	1	1
1/4/2008	4:15 PM	Same Direction – Rear End	Dusk		Dry	0	2
1/25/2008	1:45 PM	Pedestrian	Daylight		Dry	0	2
2/5/2008	6:24 PM	Struck Parked Vehicle	Dark (Street Lights On /Continuous)	Property Damage	Wet	1	2
4/8/2008	9:04 PM	Backing	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	1
4/17/2008	12:16 AM	Pedestrian	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	2
4/19/2008	5:10 PM	Struck Parked Vehicle	Daylight	Property Damage	Dry	0	2
5/9/2008	12:03 PM	Struck Parked Vehicle	Daylight	Property Damage	Wet	0	1

CRASH DATE	CRASH TIME	CRASH TYPE	LIGHT CONDITION	SEVERITY	SURFACE CONDITION	TOTAL INJURED	TOTAL VEHICLES INVOLVED
5/16/2008	8:12 PM	Pedestrian	Dark (Street Lights On /Continuous)	Injury	Wet	0	2
6/22/2008	1:56 PM	Same Direction – Rear End	Daylight	Property Damage	Dry	0	2
6/30/2008	8:16 PM	Right Angle	Dusk	Property Damage	Dry	1	2
7/2/2008	12:04 PM	Backing	Daylight	Property Damage	Dry	1	1
7/10/2008	4:52 PM	Right Angle	Daylight	Property Damage	Dry	0	2
7/17/2008	4:58 PM	Right Angle	Daylight	Property Damage	Dry	0	2
7/18/2008	5:50 PM	Right Angle	Daylight	Property Damage	Dry	0	2
9/8/2008	4:51 PM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	2
9/17/2008	9:18 PM	Struck Parked Vehicle	Dark (Street Lights On /Continuous)		Dry	0	2
10/23/2008	6:22 PM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	1	1
10/25/2008	6:38 PM	Pedestrian	Dark (Street Lights On /Continuous)	Injury	Wet	0	2
12/13/2008	1:12 AM	Backing	Dark (Street Lights Off)	Property Damage	Dry	0	2
12/30/2008	6:03 PM	Same Direction – Side Swipe	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	2
1/27/2009	11:31 PM	Same Direction – Rear End	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	2
3/15/2009	12:01 PM	Right Angle	Daylight		Dry	0	2
3/31/2009	10:42 PM	Same Direction – Rear End	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	2
4/19/2009	9:52 PM	Backing	Dark (Street Lights On /Spot)	Property Damage	Dry	0	2
5/21/2009	2:12 PM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	2
7/17/2009	2:15 PM	Left Turn / U-Turn	Daylight	Property Damage	Dry	0	2
8/11/2009	9:29 AM	Same Direction – Rear End	Daylight	Property Damage	Dry	0	2
8/19/2009	2:40 PM	Same Direction – Rear End	Daylight	Property Damage	Dry	0	2
10/19/2009	1:36 PM	Left Turn / U-Turn	Daylight	Property Damage	Dry	0	2
10/23/2009	5:40 PM	Same Direction – Side Swipe	Dawn	Property Damage	Wet	0	2
11/19/2009	6:27 PM	Same Direction – Side Swipe	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	2

### *Somerset Street & College Avenue*

CRASH DATE	CRASH TIME	CRASH TYPE	LIGHT CONDITION	SEVERITY	SURFACE CONDITION	TOTAL INJURED	TOTAL PEDES-TRIANS INVOLVED
2/20/2007	8:14 PM	Struck Parked Vehicle	Dark (Street Lights On /Continuous)		Wet	0	0
7/24/2007	8:31 AM	Pedestrian	Daylight	Injury	Dry	1	1
8/28/2007	2:28 PM	Right Angle	Daylight	Property Damage	Dry	0	0
4/16/2008	1:04 PM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	0
5/3/2008	12:53 AM	Right Angle	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	0
9/12/2008	6:50 PM	Right Angle	Dark (Street Lights On /Continuous)	Property Damage	Wet	0	0
2/10/2009	5:49 PM	Same Direction – Rear End	Dusk	Property Damage	Dry	0	0
4/28/2009	2:06 PM	Same Direction – Rear End	Daylight	Property Damage	Dry	0	0
5/29/2009	5:40 AM	Right Angle	Dark (Street Lights On /Continuous)	Property Damage	Wet	0	0
10/10/2009	11:54 PM	NULL	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	0

### *Somerset Street & Wall Street*

CRASH DATE	CRASH TIME	CRASH TYPE	LIGHT CONDITION	SEVERITY	SURFACE CONDITION	TOTAL INJURED	TOTAL PEDES-TRIANS INVOLVED
9/4/2008	2:53 PM	Struck Parked Vehicle	Daylight	Property Damage	Dry	1	0
10/16/2008	8:12 PM	Same Direction – Rear End	Dark (Street Lights On /Continuous)	Injury	Dry	0	0
12/26/2008	5:02 PM	Struck Parked Vehicle	Daylight	Property Damage	Dry	0	0
1/27/2009	4:00 PM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	0
4/6/2009	3:31 PM	Same Direction – Rear End	Daylight	Property Damage	Wet	0	0
9/15/2009	5:36 PM	Right Angle	Daylight	Property Damage	Dry	0	0

### Somerset Street & George Street (CR 672)

CRASH DATE	CRASH TIME	CRASH TYPE	LIGHT CONDITION	SEVERITY	SURFACE CONDITION	TOTAL INJURED	TOTAL PEDESTRIANS INVOLVED	PEDESTRIANS INJURED
5/11/2007	7:19 PM	Fixed Object	Daylight	Property Damage	Dry	0	0	0
8/21/2007	2:53 PM	Same Direction – Side Swipe	Daylight	Property Damage	Wet	1	1	0
9/7/2007	2:47 PM	Fixed Object	Daylight	Property Damage	Dry	0	0	0
9/27/2007	9:15 AM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	0	0
10/5/2007	6:46 PM	Same Direction – Rear End	Daylight	Property Damage	Dry	0	0	0
11/26/2007	7:53 PM	Pedestrian	Dark (Street Lights On /Continuous)	Injury	Wet	0	0	0
11/26/2007	6:39 PM	Same Direction – Side Swipe	Dark (Street Lights On /Continuous)	Property Damage	Wet	0	0	0
1/29/2008	7:52 PM	Pedestrian	Dark (Street Lights On /Continuous)	Injury	Dry	0	0	1
4/13/2008	12:45 AM	Same Direction – Side Swipe	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	0	0
5/24/2008	10:03 PM	Same Direction – Side Swipe	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	0	0
5/30/2008	11:14 PM	Same Direction – Rear End	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	0	0
8/5/2008	2:49 PM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	0	0
9/8/2008	3:34 PM	Backing	Daylight	Property Damage	Dry	0	1	0
12/6/2008	11:02 PM	Right Angle	Dark (Street Lights On /Continuous)	Property Damage	Wet	0	0	0
12/22/2008	9:32 AM	Pedestrian	Daylight	Property Damage	Icy	1	1	0
1/2/2009	7:42 PM	Struck Parked Vehicle	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	0	0
1/31/2009	7:27 PM	Same Direction – Rear End	Dark (Street Lights On /Spot)	Property Damage	Dry	0	0	0
2/17/2009	7:56 PM	Same Direction – Rear End	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	0	0
4/5/2009	12:03 PM	Right Angle	Daylight	Property Damage	Dry	0	0	0
11/14/2009	5:14 PM	Same Direction – Rear End	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	0	0

***George Street (CR 672/171) & Albany Street (Route 27)***

CRASH DATE	CRASH TIME	CRASH TYPE	LIGHT CONDITION	SEVERITY	SURFACE CONDI-TION	TOTAL INJURED	TOTAL PEDES-TRIANS INVOLVED
2/26/2007	10:38 AM	Same Direction – Rear End	Daylight	Injury	Wet	0	0
2/27/2007	12:52 PM	Backing	Daylight	Property Damage	Dry	0	0
3/22/2007	4:56 PM	Same Direction – Rear End	Daylight	Property Damage	Dry	0	0
4/27/2007	11:26 PM	Same Direction – Rear End	Dark (Street Lights On /Continuous)	Property Damage	Dry	1	0
5/14/2007	6:49 PM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	0
5/24/2007	3:18 AM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	0
5/29/2007	10:29 AM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	0
5/29/2007	2:40 PM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	0
6/9/2007	11:17 AM	Same Direction – Rear End	Daylight	Injury	Dry	1	0
7/11/2007	10:16 PM	Same Direction – Rear End	Dark (Street Lights On /Continuous)	Injury	Dry	0	0
7/26/2007	8:23 AM	Same Direction – Rear End	Daylight	Property Damage	Dry	0	0
7/29/2007	2:28 AM	Same Direction – Rear End	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	0
8/2/2007	5:27 PM	Same Direction – Rear End	Daylight	Property Damage	Dry	1	1
8/2/2007	2:26 PM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	0
9/17/2007	9:04 AM	Pedestrian	Daylight	Injury	Dry	0	0
9/18/2007	8:42 PM	Left Turn / U-Turn	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	0
10/3/2007	1:47 PM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	0
10/7/2007	1:28 PM	Same Direction – Rear End	Daylight	Property Damage	Dry	0	0
10/22/2007	12:31 PM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	0
12/7/2007	7:11 PM	Pedestrian	Dark (No Street Lights)		Dry	0	0
1/7/2008	10:17 AM	Pedestrian	Daylight	Property Damage	Dry	0	0

CRASH DATE	CRASH TIME	CRASH TYPE	LIGHT CONDITION	SEVERITY	SURFACE CONDITION	TOTAL INJURED	TOTAL PEDESTRIANS INVOLVED
3/7/2008	3:05 AM	Right Angle	Dark (Street Lights On /Continuous)	Injury	Dry	0	0
4/8/2008	8:22 AM	Other	Daylight	Property Damage	Dry	2	0
4/12/2008	1:36 PM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	0
4/17/2008	5:28 PM	Same Direction – Rear End	Daylight	Property Damage	Dry	0	0
4/18/2008	4:39 PM	Struck Parked Vehicle	Daylight	Property Damage	Dry	0	0
4/24/2008	6:48 AM	Same Direction – Rear End	Daylight		Dry	0	0
5/26/2008	3:02 PM	Same Direction – Rear End	Daylight	Property Damage	Unknown	0	0
5/29/2008	12:55 PM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	0
5/30/2008	3:37 PM	Same Direction – Rear End	Daylight	Property Damage	Dry	0	0
7/15/2008	6:43 PM	Right Angle	Daylight	Property Damage	Dry	0	0
9/9/2008	11:14 AM	Same Direction – Side Swipe	Daylight	Property Damage	Wet	0	0
10/13/2008	8:16 PM	Same Direction – Side Swipe	Dark (Street Lights On /Continuous)	Property Damage	Dry	0	0
11/5/2008	6:14 PM	Right Angle	Dark (Street Lights On /Continuous)	Property Damage	Wet	0	0
11/6/2008	12:35 PM	Same Direction – Rear End	Daylight	Property Damage	Wet	0	0
11/9/2008	2:20 PM	Other	Daylight	Property Damage	Dry	0	0
11/17/2008	4:18 PM	Right Angle	Daylight	Property Damage	Dry	0	0
11/24/2008	9:57 PM	Right Angle	Dark (Street Lights On/ Continuous)	Property Damage	Wet	0	0
12/14/2008	9:29 AM	Right Angle	Daylight	Property Damage	Dry	0	0
12/16/2008	6:25 PM	Same Direction – Side Swipe	Dusk	Property Damage	Snowy	0	0
12/23/2008	2:54 PM	Same Direction – Side Swipe	Daylight	Property Damage	Dry	0	1
4/29/2009	9:57 AM	Pedestrian	Daylight	Injury	Dry	1	2
5/13/2009	12:13 PM	Same Direction – Rear End	Daylight	Property Damage	Dry	0	0
5/15/2009	6:13 PM	Right Angle	Daylight	Property Damage	Dry	0	0




CRASH DATE	CRASH TIME	CRASH TYPE	LIGHT CONDITION	SEVERITY	SURFACE CONDITION	TOTAL INJURED	TOTAL PEDESTRIANS INVOLVED
6/6/2009	12:36 AM	Same Direction – Rear End	Dark (Street Lights On /Continuous)	Injury	Wet	1	0
7/7/2009	5:36 PM	Struck Parked Vehicle	Daylight	Injury	Dry	0	0
7/10/2009	10:25 AM	Same Direction – Rear End	Daylight	Property Damage	Dry	1	1
8/17/2009	9:03 AM	Same Direction – Rear End	Daylight		Dry	0	0
10/1/2009	2:57 PM	Same Direction – Rear End	Daylight	Property Damage	NULL	0	0
10/10/2009	11:01 PM	Pedestrian	Dark (Street Lights On /Continuous)		Dry	0	0
10/26/2009	12:57 PM	Pedestrian	Daylight	Injury	Dry	1	1
11/13/2009	12:22 AM	Right Angle	Dark (Street Lights On /Continuous)	Property Damage	Wet	1	1

# **Appendix B – Crash Diagrams**


























---




# Easton Avenue (CR 514) & Albany Street (Route 27)



## Easton Avenue (CR 514) & Albany Street (Route 27)- continued

<p><b>A Backing</b> </p> <p>1 5/13/2008 - 12:01 pm - Dry, Daylight</p>	<p><b>K Same Direction - Rear End</b> </p> <p>13 2/7/2007 - 3:31 pm - Dry, Dark (Street Lights On/ Continuous)</p> <p>14 12/26/2007 - 2:06 pm - Dry, Daylight</p>	<p><b>Q Same Direction - Side Swipe</b> </p> <p>23 2/24/2007 - 9:22 am - Dry, Dark (Street Lights On/ Continuous)</p>
<p><b>B Fixed Object</b> </p> <p>2 4/23/2007 - 10:08 pm - Dry, Dark (Street Lights On/ Continuous)</p>	<p><b>L Same Direction - Rear End</b> </p> <p>15 5/23/2007 - 8:45 pm - Dry, Dark (Street Lights On/ Continuous)</p> <p>16 11/14/2009 - 8:21 pm - Wet, Dark (Street Lights On/ Continuous)</p> <p>17 9/29/2009 - 9:55 pm - Dry, Dark (Street Lights On/ Continuous)</p>	<p><b>R Same Direction - Side Swipe</b> </p> <p>24 6/28/2007 - 7:17 pm - Wet, Daylight</p>
<p><b>C Fixed Object</b> </p> <p>3 3/8/2008 - 11:17 am - Wet, Daylight</p>	<p><b>M Same Direction - Rear End</b> </p> <p>18 8/12/2007 - 1:10 pm - Dry, Daylight</p>	<p><b>S Same Direction - Side Swipe</b> </p> <p>25 7/8/2007 - 6:16 pm - Dry, Daylight</p>
<p><b>D Left Turn / U Turn</b> </p> <p>5 2/6/2007 - 5:20 pm - Dry, Dusk</p>	<p><b>N Same Direction - Rear End</b> </p> <p>19 2/12/2008 - 3:45 pm - Snowy, Daylight</p>	<p><b>T Same Direction - Side Swipe</b> </p> <p>26 9/11/2007 - 8:06 pm - Dry, Dark (Street Lights On/ Continuous)</p>
<p><b>E Pedestrian</b> </p> <p>6 4/20/2009 - 8:22 am - Dry, Daylight</p>	<p><b>O Same Direction - Rear End</b> </p> <p>20 11/2/2007 - 7:50 am - Dry, Daylight</p>	<p><b>U Same Direction - Side Swipe</b> </p> <p>27 9/11/2007 - 4:46 pm - Dry, Daylight</p> <p>28 10/26/2007 - 4:31 pm - Wet, Daylight</p> <p>29 7/15/2008 - 5:51 pm - Dry, Daylight</p> <p>30 8/12/2009 - 5:33 pm - Dry, Daylight</p>
<p><b>F Pedestrian</b> </p> <p>7 7/29/2009 - 9:54 am - Dry, Daylight</p> <p>8 2/18/2009 - 2:43 pm - Wet, Daylight</p>	<p><b>P Same Direction - Rear End</b> </p> <p>21 7/20/2008 - 5:58 pm - Dry, Daylight</p> <p>22 8/23/2008 - 9:32 am - Dry, Daylight</p>	<p><b>V Same Direction - Side Swipe</b> </p> <p>31 1/30/2009 - 4:37 pm - Dry, Daylight</p>
<p><b>G Pedestrian</b> </p> <p>9 9/13/2009 - 3:12 am - Wet, Dark (Street Lights On/ Continuous)</p>	<p><b>No Information Available to Diagram Crash</b></p> <p>35 <b>Struck Parked Vehicle</b> - 4/18/2008 - 4:39 pm - Dry, Daylight</p> <p>36 <b>Struck Parked Vehicle</b> - 12/11/2008 - 9:42 am - Wet, Daylight</p> <p>37 <b>Pedacyclist</b> - 4/23/2007 - 9:53 pm - Dry, Dark (Street Lights On/ Continuous)</p>	<p><b>W Same Direction - Side Swipe</b> </p> <p>32 10/16/2009 - 5:32 pm - Wet, Daylight</p> <p>33 4/24/2008 - 10:28 am - Dry, Daylight</p>
<p><b>H Right Angle</b> </p> <p>10 11/26/2007 - 8:25 pm - Wet, Dark (Street Lights On/ Spot)</p>		<p><b>X Struck Parked Vehicle</b> </p> <p>34 2/2/2007 - 11:01 am - Dry, Daylight</p>
<p><b>I Right Angle</b> </p> <p>11 8/14/2008 - 12:15 pm - Dry, Daylight</p>		<p><b>Z Fixed Object</b> </p> <p>4 10/12/2008 - 2:01 am - Dry, Dark (Street Lights On/ Continuous) (DUI)</p>
<p><b>J Right Angle</b> </p> <p>12 6/17/2009 - 2:34 pm - Unknown, Daylight</p>		

# Easton Avenue (CR 514) & Wall Street/Little Albany Street




*Easton Avenue (CR 514) & Wall Street/Little Albany Street – continued*

- A **Fixed Object** 
  - 1 5/29/2008 - 2:31 pm - Dry, Daylight
  
- B **Left Turn / U Turn** 
  - 2 3/23/2009 - 2:31 pm - Dry, Daylight
  
- C **Pedalcyclist** 
  - 3 10/20/2009 - 4:01 pm - Dry, Daylight
  
- D **Pedestrian** 
  - 4 2/13/2008 - 7:16 am - Dry, Daylight
  
- E **Right Angle** 
  - 5 2/25/2007 - 9:08 pm - Dry, Dark (Street Lights On/ Continuous)
  
- F **Right Angle** 
  - 6 11/14/2007 - 8:03 am - Icy, Daylight
  
- G **Right Angle** 
  - 7 11/12/2008 - 1:15 pm - Dry, Daylight
  - 8 11/4/2009 - 7:22 am - Dry, Daylight
  
- H **Right Angle** 
  - 9 12/18/2008 - 2:54 pm - Wet, Daylight
  
- I **Same Direction - Rear End** 
  - 10 5/14/2007 - 12:50 pm - Dry, Daylight
  
- J **Same Direction - Rear End** 
  - 11 2/22/2008 - 1:35 am - Dry, Dark (Street Lights On/ Continuous)
  
- K **Same Direction - Rear End** 
  - 12 4/6/2009 - 1:07 pm - Wet, Daylight
  
- L **Same Direction - Rear End** 
  - 13 7/14/2009 - 1:58 pm - Dry, Daylight
  
- No Direction of Travel Specified**
  - 14 Same Direction Rear End - 12/2/2007 - 7:32 am - Dry, Daylight
  
- N **Same Direction - Side Swipe** 
  - 15 5/22/2008 - 6:42 pm - Dry, Daylight
  
- O **Same Direction - Side Swipe** 
  - 16 2/24/2009 - 6:56 am - Dry, Daylight
  
- P **Struck Parked Vehicle** 
  - 17 8/28/2007 - 2:44 pm - Dry, Daylight
  - 18 3/5/2008 - 12:31 pm - Snowy, Daylight
  - 19 7/7/2009 - 1:01 pm - Daylight, Null



# Easton Avenue (CR 514) & Somerset Street






## Easton Avenue (CR 514) & Somerset Street – continued

- A Backing** ●
- 1 1/15/2007 - 12:12 pm - Wet, Daylight
- B Backing** ●
- 2 10/7/2007 - 2:46 pm - Dry, Daylight
- C Backing** ○
- 3 4/8/2008 - 9:04 pm - Dry, Dark (Street Lights On/ Continuous)
- D Backing** ●
- 4 7/2/2008 - 12:04 pm - Dry, Daylight
- 5 12/13/2008 - 1:12 am - Dry, Dark (Street Lights Off)
- E Left Turn / U Turn** ●
- 6 **2/2/2007 - 10:43 pm - Wet, Dark (Street Lights On/ Continuous)**
- 7 7/17/2009 - 2:15 pm - Dry, Daylight
- 8 10/19/2009 - 1:36 pm - Dry, Daylight
- F Opposite Direction - Side Swipe** ●
- 9 9/8/2007 - 1:11 am - Dry, Dark (Street Lights On/ Continuous)
- G Pedestrian** ●
- 10 **2/28/2007 - 6:06 am - Dry, Street Lights On/ Continuous)**
- H Pedestrian** ●
- 11 1/25/2008 - 1:45 pm - Dry, Daylight
- I Pedestrian** ●
- 12 4/17/2008 - 12:16 am - Dry, Dark (Street Lights On/ Continuous)
- J Pedestrian** ●
- 13 **10/25/2008 - 6:38 pm - Wet, Dark (Street Lights On/ Continuous)**
- K Right Angle** ●
- 14 7/10/2008 - 4:52 pm - Dry, Daylight
- 15 3/15/2009 - 12:01 pm - Dry, Daylight
- L Right Angle** ●
- 16 7/17/2008 - 4:58 pm - Dry, Daylight
- M Right Angle** ●
- 17 7/18/2008 - 5:50 pm - Dry, Daylight
- N Same Direction - Rear End** ●
- 18 **1/19/2007 - 6:44 pm - Dry, Dark (Street Lights On/ Continuous)**
- 19 1/4/2008 - 4:15 pm - Dry, Dusk
- 20 3/31/2009 - 10:42 pm - Dry, Dark (Street Lights On/ Continuous)
- O Same Direction - Rear End** ●
- 21 10/4/2007 - 4:03 pm - Dry, Daylight
- 22 8/11/2009 - 9:29 am - Dry, Daylight
- P Same Direction - Rear End** ●
- 23 6/22/2008 - 1:56 pm - Dry, Daylight
- 24 1/27/2009 - 11:31 pm - Dry, Dark (Street Lights On/ Continuous)
- Q Same Direction - Rear End** ●
- 25 8/19/2009 - 2:40 pm - Dry, Daylight
- 26 6/30/2008 - 8:16 pm - Dry, Dusk (Coded as Right Angle)
- R Same Direction - Side Swipe** ●
- 27 7/5/2007 - 5:36 pm - Wet, Daylight
- 28 7/27/2007 - 6:16 pm - Dry, Daylight
- 29 9/8/2008 - 4:51 pm - Dry, Daylight
- 30 12/30/2008 - 6:03 pm - Dry, Dark (Street Lights On/ Continuous)
- 31 10/23/2008 - 6:22 pm - Dry, Daylight
- 32 11/19/2009 - 6:27 pm - Dry, Dark (Street Lights On/ Continuous)
- S Same Direction - Side Swipe** ●
- 33 8/8/2007 - 5:02 pm - Dry, Daylight
- 34 10/23/2009 - 5:40 pm - Wet, Dawn
- T Same Direction - Side Swipe** ●
- 35 8/12/2007 - 4:07 pm - Dry, Daylight
- U Same Direction - Side Swipe** ●
- 36 3/31/2007 - 4:07 pm - Dry, Daylight
- 37 5/21/2009 - 2:12 pm - Dry, Daylight
- V Struck Parked Vehicle** ●
- 38 4/19/2008 - 5:10 pm - Dry, Daylight
- 39 9/17/2008 - 9:18 pm - Dry, Dark (Street Lights On/ Continuous)
- 40 5/8/2007 - 9:29 am - Dry, Daylight
- W Struck Parked Vehicle** ●
- 41 10/8/2007 - 10:17 am - Dry, Daylight
- 42 8/2/2007 - 12:57 am - Dry, Dark (Street Lights On/ Continuous)
- 43 2/5/2008 - 6:24 pm - Wet, Dark (Street Lights On/ Continuous)
- X Struck Parked Vehicle** ●
- 44 5/9/2008 - 12:03 pm - Wet, Daylight
- No Direction of Travel or Location Specified**
- 45 Backing - 4/19/2009 - 9:52 pm - Dry, Dark (Street Lights On/ Spot)
- 46 Pedestrian - 5/16/2008 - 8:12 pm - Wet, Dark (Street Lights On/ Continuous)

## Somerset Street & College Avenue

- (A) **Pedestrian** ●
- (1) 7/24/2007 - 8:31 am - Dry, Daylight
- (B) **Right Angle** ●
- (2) 8/28/2007 - 2:28 pm - Dry, Daylight
- (C) **Right Angle** ●
- (3) 5/3/2008 - 12:53 am - Dry, Dark (Street Lights On/ Continuous)
- (4) 9/12/2008 - 6:50 pm - Wet, Dark (Street Lights On/ Continuous)
- (D) **Right Angle** ●
- (5) 5/29/2009 - 5:40 am - Wet, Dark (Street Lights On/ Continuous)
- (E) **Same Direction - Rear End** ●
- (6) 2/10/2009 - 5:49 pm - Dry, Dusk
- (F) **Same Direction - Rear End** ●
- (7) 4/28/2009 - 2:06 pm - Dry, Daylight
- (8) 10/10/2009 - 11:54 pm - Dry, Dark (Street Lights On/ Continuous)  
-involved 3 vehicles; classified as NULL crash
- (G) **Same Direction - Side Swipe** ●
- (9) 4/16/2008 - 1:04 pm - Dry, Daylight
- (H) **Struck Parked Vehicle** ●
- (10) 2/20/2007 - 8:14 pm - Wet, Dark (Street Lights On/ Continuous)




**LEGEND**

**Injury** (bold)

● No. of crashes by type (if >1)

## Somerset Street & Wall Street

- A** Right Angle ●
  - ① 9/15/2009 - 5:36 pm - Dry, Daylight
- B** Same Direction - Rear End ●
  - ② 4/6/2009 - 3:31 pm - Wet, Daylight
- C** Same Direction - Rear End ●
  - ③ **10/16/2008 - 8:12 pm - Dry, Dark (Street Lights On/ Continuous)**
- D** Same Direction - Side Swipe ●
  - ④ 1/27/2009 - 4:00 pm - Dry, Daylight
- E** Struck Parked Vehicle ●
  - ⑤ 9/4/2008 - 2:53 pm - Dry, Daylight
  - ⑥ 12/26/2008 - 5:02 pm - Dry, Daylight




**LEGEND**

**Injury** (bold)

ⓧ No. of crashes by type (if >1)

# Somerset Street & George Street (CR 672)

- A **Fixed Object** ●
- 1 5/11/2007 - 7:19 pm - Dry, Daylight
- B **Fixed Object** ●
- 2 9/7/2007 - 2:47 pm - Dry, Daylight
- C **Pedestrian** ●
- 3 11/26/2007 - 7:53 pm - Wet, Dark (Street Lights On/ Continuous)
- 4 1/29/2008 - 7:52 pm - Dry, Dark (Street Lights On/ Continuous)
- 5 12/22/2008 - 9:32 am - Icy, Daylight
- D **Right Angle** ●
- 6 12/6/2008 - 11:02 pm - Wet, Dark (Street Lights On/ Continuous)
- 7 4/5/2009 - 12:03 pm - Dry, Daylight
- E **Same Direction - Rear End** ●
- 8 10/5/2007 - 6:46 pm - Dry, Daylight
- 9 5/30/2008 - 11:14 pm - Dry, Dark (Street Lights On/ Continuous)
- F **Same Direction - Rear End** ●
- 10 1/31/2009 - 7:27 pm - Dry, Dark (Street Lights On/ Continuous)
- G **Same Direction - Rear End** ●
- 11 2/17/2009 - 7:56 pm - Dry, Dark (Street Lights On/ Continuous)
- H **Same Direction - Side Swipe** ●
- 12 8/21/2007 - 2:53 pm - Wet, Daylight
- 13 5/24/2008 - 10:03 pm - Dry, Dark (Street Lights On/ Continuous)
- 14 11/26/2007 - 6:39 pm - Wet, Dark (Street Lights On/ Continuous)
- 15 4/13/2008 - 12:45 am - Dry, Dark (Street Lights On/ Continuous)
- I **Same Direction - Side Swipe** ●
- 16 9/27/2007 - 9:15 am - Dry, Daylight
- J **Same Direction - Side Swipe** ●
- 17 8/5/2008 - 2:49 pm - Dry, Daylight
- K **Struck Parked Vehicle** ●
- 18 1/2/2009 - 7:42 pm - Dry, Dark (Street Lights On/ Continuous)
- G **No Location or Direction of Travel Specified**
- 19 **Backing** - 9/8/2008 - 3:34 pm - Dry, Daylight
- 20 **Same Direction - Rear End** - 11/14/2009 - 5:14 pm - Dry, Dark (Street Lights On/ Continuous)



**LEGEND**

**Injury** (bold)

⊗ No. of crashes by type (if >1)

# George Street (CR 672/171) & Albany Street (Route 27)


- A Backing
- B Left Turn / U Turn
- C Other
- D Pedestrian
- E Pedestrian
- F Pedestrian
- G Pedestrian

- H Right Angle
- I Right Angle
- J Right Angle
- K Right Angle
- L Right Angle

- M Same Direction - Rear End
- N Same Direction - Rear End
- O Same Direction - Rear End
- P Same Direction - Rear End
- Q Same Direction - Rear End
- R Same Direction - Rear End
- S Same Direction - Rear End




























**LEGEND**

(X) No. of crashes by type (if >1)



- T Same Direction - Side Swipe
- U Same Direction - Side Swipe
- V Same Direction - Side Swipe
- W Same Direction - Side Swipe
- X Same Direction - Side Swipe
- Y Same Direction - Side Swipe
- Z Same Direction - Side Swipe
- aa Struck Parked Vehicle
- bb Struck Parked Vehicle

## George Street (CR 672/171) & Albany Street (Route 27) – continued

- A Backing** 
- 1 2/27/2007 - 12:52 pm - Dry, Daylight
- B Left Turn / U Turn** 
- 2 9/18/2007 - 8:42 pm - Dry, Dark (Street Lights On/ Continuous)
- C Other NO DIRECTION OR SPECIFIC LOCATION NOTED**
- 3 4/8/2008 - 8:22 am - Dry, Daylight  
(Same direction rear end-3 cars)
- 4 11/9/2008 - 2:20pm - Dry, Daylight  
(Hit open passenger door)
- D Pedestrian** 
- 5 9/17/2007 - 9:04 am - Dry, Daylight
- 6 10/10/2009 - 11:01 pm - Dry, Dark (Street Lights On/ Continuous)
- 7 10/26/2009 - 12:57 pm - Dry, Daylight
- E Pedestrian** 
- 8 12/7/2007 - 7:11 pm - Dry, Dark (No Street Lights)
- F Pedestrian** 
- 9 1/7/2008 - 10:17 am - Dry, Daylight
- G Pedestrian** 
- 10 4/29/2009 - 9:57 am - Dry, Daylight
- H Right Angle** 
- 11 3/7/2008 - 3:05 am - Dry, Dark (Street Lights On/ Continuous)
- 12 11/13/2009 - 12:22 am - Wet, Dark (Street Lights On/ Continuous)
- I Right Angle** 
- 13 11/24/2008 - 9:57 pm - Wet, Dark (Street Lights On/ Continuous)
- 14 5/15/2009 - 6:13 pm - Dry, Daylight
- J Right Angle** 
- 15 7/15/2008 - 6:43 pm - Dry, Daylight
- K Right Angle** 
- 16 11/5/2008 - 6:14 pm - Wet, Dark (Street Lights On/ Continuous)
- 17 11/17/2008 - 4:18 pm - Dry, Daylight
- L Right Angle** 
- 18 12/14/2008 - 9:29 am - Dry, Daylight
- M Same Direction - Rear End** 
- 19 2/26/2007 - 10:38 am - Wet, Daylight
- 20 8/2/2007 - 5:27 pm - Dry, Daylight
- N Same Direction - Rear End** 
- 21 3/22/2007 - 4:56 pm - Dry, Daylight
- 22 6/9/2007 - 11:17 am - Dry, Daylight
- 23 4/24/2008 - 6:48 am - Dry, Daylight
- 24 7/10/2009 - 10:25 am - Dry, Daylight
- O Same Direction - Rear End** 
- 25 4/27/2007 - 11:26 pm - Dry, Dark (Street Lights On/ Continuous)
- 26 7/11/2007 - 10:16 pm - Dry, Dark (Street Lights On/ Continuous)
- 27 4/17/2008 - 5:28 pm - Dry, Daylight
- 28 5/30/2008 - 3:37 pm - Dry, Daylight
- 29 8/17/2009 - 9:03 am - Dry, Daylight
- 30 5/13/2009 - 12:13 pm - Dry, Daylight
- P Same Direction - Rear End** 
- 31 10/7/2007 - 1:28 pm - Dry, Daylight
- 32 7/29/2007 - 2:28 am - Dry, Dark (Street Lights On/ Continuous)
- 33 7/26/2007 - 8:23 am - Dry, Daylight
- Q Same Direction - Rear End** 
- 34 5/26/2008 - 3:02 pm - Unknown, Daylight
- R Same Direction - Rear End** 
- 35 11/6/2008 - 12:35 pm - Wet, Daylight
- S Same Direction - Rear End** 
- 36 10/1/2009 - 2:57 pm - Null, Daylight
- Same Direction - Side Swipe**  
**NO DIRECTION OR SPECIFIC LOCATION NOTED**
- 37 6/6/2009 - 12:36 am - Wet, Dark (Street Lights On/ Continuous)
- T Same Direction - Side Swipe** 
- 38 5/14/2007 - 6:49 pm - Dry, Daylight
- 39 10/3/2007 - 1:47 pm - Dry, Daylight
- U Same Direction - Side Swipe** 
- 40 5/24/2007 - 3:18 am - Dry, Daylight
- 41 10/22/2007 - 12:31 pm - Dry, Daylight
- V Same Direction - Side Swipe** 
- 42 5/29/2007 - 10:29 am - Dry, Daylight
- W Same Direction - Side Swipe** 
- 43 4/12/2008 - 1:36 pm - Dry, Daylight
- X Same Direction - Side Swipe** 
- 44 8/2/2007 - 2:26 pm - Dry, Daylight
- Y Same Direction - Side Swipe** 
- 45 12/16/2008 - 6:25 pm - Snowy, Dusk
- Z Same Direction - Side Swipe** 
- 46 10/13/2008 - 8:16 pm - Dry, Dark (Street Lights On/ Continuous)
- 47 12/23/2008 - 2:54 pm - Dry, Daylight
- Same Direction - Side Swipe**  
**NO DIRECTION OR SPECIFIC LOCATION NOTED**
- 48 5/29/2008 - 12:55 pm - Dry, Daylight
- 49 9/9/2008 - 11:14 am - Wet, Daylight
- 50 5/29/2007 - 2:40 pm - Dry, Daylight
- aa Struck Parked Vehicle** 
- 51 4/18/2008 - 4:39 pm - Dry, Daylight
- bb Struck Parked Vehicle** 
- 52 7/7/2009 - 5:36 pm - Dry, Daylight




# Appendix C – Straight Line Diagrams



# Easton Avenue (CR 514)

ROUTE 514 (West to East)

Mile Posts: 23.000 - 24.590




SRI = 0000514\_\_

Date last inventoried: August 2006

# Albany Street (NJ 27)

NJ 27 (South to North)

Mile Posts: 14.000 - 17.000




SRI = 0000027\_\_

Date last inventoried: April 2010

# College Avenue

## COLLEGE AVE (South to North)

Mile Posts: 0.000 - 0.750



SRI = 12141220\_\_



Date last inventoried: December 1999

Page Created: May 2010

# Somerset Street

**SOMERSET ST (South to North)**

**Mile Posts: 0.000 - 0.170**



Street Name	Somerset Street
Jurisdiction	Municipal
Functional Class	Urban Collector
Federal Aid - NHS Sy	STP
Control Section	Begin Somerset St (MP=0) / End Somerset St (MP=0.17)
Speed Limit	25
Number of Lanes	2
Med. Type	None
Med. Width	0
Pavement	40
Shoulder	0
Traffic Volume	
Traffic Sta. ID	
Structure No.	
Enlarged Views	

SRI = 12141221\_

Date last inventoried: December 1999


Page Created: May 2010



# George Street (CR 672)

MIDDLESEX COUNTY 672 (South to North)

Mile Posts: 0.700 - 1.470




SRI = 12000672\_

Date last inventoried: December 1999

# George Street (CR 171)

NJ 171 (South to North)

Mile Posts: 2.000 - 3.100





SRI = 0000171\_\_





Date last inventoried: March 2008



# Appendix D – Jurisdictional Map






LEGEND		
Jurisdiction	Roadway	Intersection
Middlesex County		
City of New Brunswick		

# **Appendix E – Bus Map**

---



Bus Route Number	Bus Route	Route Color
810	New Brunswick – Woodbridge Center	Med Green
811	New Brunswick – South River	Dark Green
814	North Brunswick – New Brunswick – Middlesex County College	Lighter Green
815	New Brunswick – East Brunswick – Woodbridge Center	Navy Blue


Bus Route Number	Bus Route	Route Color
818	New Brunswick – East Brunswick – Old Bridge	Chartreuse
M1	New Brunswick – Jamesburg 8A Shuttle	Medium Blue
M4	Brunswick – Jersey Avenue Shuttle	Brown
M5	Brunswick – Commercial Avenue Shuttle	Red

# Appendix F – Summary of Proposed Diagrams





**Recommendation - Somerset Street & College Avenue**



**Recommendation – Somerset Street & George Street**

